



State of Ohio Environmental Protection Agency

North

OH7004712

SHILOH VILLAGE OF

6/8/2010

347 North Dunbridge Rd.  
Bowling Green, OH 43402-9398

TELE: (41



rnor  
rnor  
ctor

Re: Richland County  
Village of Shiloh  
Community Water System  
PWS ID# OH7004712

June 8, 2010

Mr. Rick Reeder, Village Administrator  
Village of Shiloh  
P. O. Box 242  
Shiloh, Ohio 44878-0242

Dear Mr. Reeder:

Ohio Administrative Code, Rule 3745-83-01 requires that each community and major non-community water system maintain a minimum of 0.2 mg/l free chlorine residual measured at representative points throughout the distribution system

Review of your February 2010 operational reports indicate that free chlorine residuals were below this level a total of 7 days in February 2010.

An investigation needs to be made to find the cause of these low chlorine residuals and steps need to be taken to bring the water system back to compliance with OAC Rule 3745-83-01.

Please note that additional information concerning existing and upcoming drinking water regulations and requirements can be obtained from our Web site at <http://www.epa.ohio.gov>. If you have any questions regarding this letter, or any other matter involving your water system, please feel free to contact me at 419-373-3105 or via email at [curt.eldridge@epa.state.oh.us](mailto:curt.eldridge@epa.state.oh.us).

Yours truly

Curtis A. Eldridge  
Environmental Specialist 2  
Division of Drinking and Ground Water

/cs

pc: Richland County Health Department  
(DDAGW;NWDO:File)