



State of Ohio Environmental Protection Agency

Northwe:

OH7201012

SHOREWOOD VILLAGE SUBDIVISION

6/9/2010

347 North Dunbridge Rd.
Bowling Green, OH 43402-9398

TELE: (419) 32
ww



Re: Sandusky County
Shorewood Village Subdivision
PWS ID#OH7201012
STU ID#:7257906

June 9, 2010

Mr. Thomas Frey
Sandusky County Sanitary Engineer Department
2100 Countryside Place
Fremont, Ohio 43420

Dear Mr. Frey:

The Plant – Distribution Monthly Operation Report (MOR) (EPA Form 5002) was received by Ohio EPA on May 11, 2010.

Ohio Administrative Code (OAC) Rule 3745-83-01(I)(2) requires the operation report to be submitted to the district office no later than the tenth of the month following the month for which the report was prepared and also requires the report to be signed by the operator in responsible charge designated in accordance with rule 3745-7-02 of the Administrative Code.

Failure to take action to address this deficiency may result in enforcement action being taken.

Questions may be directed to my attention by contacting me at 419-373-3042 or via e-mail to larry.moritz@epa.state.oh.us.

Sincerely,

Larry W. Moritz, R.S., M.S.I.H.
Division of Drinking and Ground Waters

/cs

pc: Sandusky County Health Department
DDAGW;NWDO File

