



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

April 17, 2008

RE: HOLMES COUNTY  
CLARK TOWNSHIP  
HOMESTEAD RESTAURANT  
4450 SR 557  
NPDES 3PR00194

Mr. Ann DeHass  
P.O. Box 129  
Charm, OH 44617

Dear Ms. DeHass:

On April 16, 2008, this office conducted an inspection of the wastewater treatment plant serving the above referenced facility. Present during the inspection were this writer, Kraig Bucklew of the Holmes County Health Department, and Kevin Dean, Wastewater Treatment Plant Operator, Dean's Backflow Services.

At the time of the inspection, the treatment plant was producing what appeared to be a satisfactory quality effluent. The mixed liquor in the aeration tank had a good color and the contents of the clarifier were clear. The surface sand filter beds were in very good condition and the plant was producing a clear effluent.

A review of your self-monitoring reports covering the period September 2007 through March 2008 revealed the following effluent violation:

Reporting Period	Station	Parameter	Limit Type	Limit	Reported Value	Violation Date
February 2008	001	pH	1D Conc	9.0	9.27	2/26/2008

Overall, the results of the inspection were satisfactory. Should you have any questions or comments regarding this letter, please contact this office at (330) 963-1197.

Sincerely,

Dean W. Stoll, P.E.  
Environmental Engineer  
Division of Surface Water

DWS/mt

cc: Kraig Bucklew, Holmes County Health Department  
Kevin Dean

File: Semi-Public/Homestead Restaurant