



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

June 9, 2009

Re: Pretreatment
Cooper Standard Automotive
Village Of New Lexington
Permit No. ODP00013*EP
Noncompliance Notification

Mr. Dan Wing, Health, Safety & Env. Coordinator
Cooper Standard Automotive, Inc.
2378 S.R. 345 NE
New Lexington, Ohio 43764

Dear Mr. Wing:

We have received your industrial user monitoring report for the July through December 2008 reporting period. Our review indicates violations of the conditions of your Indirect Discharge Permit. The specific instances of noncompliance and/or deficiencies are as follows:

Station	Reporting Code	Parameter	Limit Type	Limit	Reported Value	Violation Date
001	01092	Zinc, Total (Zn)	30D Qty	0.024	.05932	8/1/2008
001	01092	Zinc, Total (Zn)	1D Qty	0.073	.18921	8/5/2008
001	01092	Zinc, Total (Zn)	30D Qty	0.024	.02532	12/1/2008

Please be advised that failure to comply with the effluent limitations or to satisfy the monitoring or reporting requirements of your Indirect Discharge Permit may be cause for enforcement action pursuant to the Ohio Revised Code Chapter 6111.

We have reviewed your report addressing the reasons for the above violations and the actions being taken to prevent further occurrences. Hopefully, these actions will prevent any recurrence so that enforcement action will not be required. No additional information is requested at this time.

If there are any questions, please contact me at (740) 380-5423.

Sincerely,

Fred J. Snell
Pretreatment Coordinator
Division of Surface Water

FS/dh

c: Mark Cooper, Superintendent, Village of New Lexington WWTP
c: Pretreatment Unit, DSW, CO