



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

February 11, 2009

**Re: Pretreatment
Plastech Engineered Products, Inc.
Village of Byesville
Compliance Inspection**

Mr. Pat Kresnak
Plastech Engineered Products, Inc.
2500 Executive Hills Road Drive
Auburn Hills, MI 48326

Dear Mr. Kresnak:

On January 14, 2009, I inspected Plastech Engineered Products, Inc. (Plastech). The inspection was conducted to evaluate the facility's compliance with federal and state pretreatment regulations and its Indirect Discharge Permit (IDP). Mark Crews, representing American Properties, was present during the inspection. Tom McVickers, Acting Utilities Superintendent, and Karen Froehlich, Wastewater Superintendent, represented the village of Byesville during the inspection. No representatives of Plastech Engineered Products were available during the inspection.

General Facility Description:

Plastech formerly manufactured plastic automotive parts. Manufacturing operations included injection molding, cleaning, painting, fabrication, assembly and packaging. Wastewaters were generated from injection mold cooling system blowdown and sand filter backwash, parts cleaning and rinse, deionizer regeneration, floor cleaning, paint rack cleaning, and paint spray booth water treatment system blowdown. All process wastewaters and a portion of sanitary wastewaters were routed to the Byesville sewer. Based on available records, it appears that Plastech discontinued manufacturing operations on June 31, 2008.

Your industrial user monitoring report for the January through June 2008 reporting period indicated violations of the conditions of your Indirect Discharge Permit. The specific instances of noncompliance and/or deficiencies are as follows:


Sample Point	Date	Parameter	Result	Units	Limit
001	1/25/08	COD	1457	mg/l	800
001	2/14/08	COD	1990	mg/l	800
001	3/24/08	COD	1134	mg/l	800

Required Actions:

1. Plastech Engineered Products holds an effective Ohio EPA Indirect Discharge Permit, ODP00016*CP. The permit requires submittal of effluent monitoring reports during the months of January and July of each year. Plastech failed to submit an effluent monitoring report in January 2009. Plastech is in violation of its IDP for failure to comply with effluent limits and reporting requirements.
2. Plastech must comply with the terms of its IDP while the permit remains effective, thus additional violations of the IDP are expected unless the IDP is revoked. Does Plastech wish to retain the IDP? If I have not received a response from Plastech requesting continuance of IDP coverage within 30 days, I will recommend that Ohio EPA revoke Plastech's IDP. A notice of revocation will be mailed to you should the Director revoke the IDP.
3. I observed wastewaters and residues remaining at the facility during the inspection. Liquids and/or sludges were present in the paint spray booth reservoir, the neutralization sump, and the outdoor paint rack cleaning pit. Drums which appeared to contain cleanup residue were also observed at the facility. These waste products present an ongoing risk of release to the environment. Plastech should arrange for lawful disposal of all remaining residues and decontamination of the holding vessels.

Please respond to this letter within 30 days. You may contact me at (740) 380-5423 with any questions.

Sincerely,



Fred J. Snell
Pretreatment Coordinator
Division of Surface Water

FJS/dh

Enclosure

- c: Karen Froehlich, Superintendent, Village of Byesville WWTP
- c: Pretreatment Unit, Ohio EPA, CO, DSW
- c: Rich Stewart, Ohio EPA, SEDO, DHWM

PRETREATMENT
Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
ODP00016*CP	OH0024287	January 14, 2009	6	S	2

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Plastech Engineered Products, Inc. 110 North Eighth Street Byesville, Ohio 43723	11:00 a.m.	September 1, 2007
	Exit Time	Permit Expiration Date
	1:00 p.m.	August 31, 2012

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
None	
Name, Address and Title of Responsible Official	Phone Number
Pat Kresnak	

C. AREAS EVALUATED DURING INSPECTION

- | | | |
|--|---|---|
| <input checked="" type="checkbox"/> M Permit | <input type="checkbox"/> N Flow Measurement | <input checked="" type="checkbox"/> M Pretreatment |
| <input checked="" type="checkbox"/> M Records/Reports | <input type="checkbox"/> N Laboratory | <input type="checkbox"/> Compliance Schedules |
| <input type="checkbox"/> U Operations & Maintenance | <input type="checkbox"/> NA Effluent/Receiving Waters | <input type="checkbox"/> NA Self-Monitoring Program |
| <input checked="" type="checkbox"/> M Facility Site Review | <input checked="" type="checkbox"/> M Sludge Storage/Disposal | <input type="checkbox"/> Other |
| <input type="checkbox"/> N Collection System | | |

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)

See attached letter.

Fred J. Snell

Fred J. Snell, Inspector, Ohio EPA, Southeast District Office

2/11/09

Date

David R. Schultz

Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

2/11/09

Date