



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

May 5, 2009

**Re: Tuscarawas County
Belden Brick Company
Notice of Violation
OIN00014, OH0008141
Correspondence (IWW)**

Mr. John Streb, Env. Associate
Belden Brick Company
State Route 39
P.O. Box 430
Sugarcreek, Ohio 44681

Dear Mr. Streb:

Ohio EPA did not receive a Discharge Monitoring Report (DMR) for your facility for outfalls 001, 004, 005, 006, 007, 008, 009, 010, 014, 016, 019, 022, 024, 025, 026, 027, 028, 029, 030, 033, 036, 037, 038, 039, 040, 041, 045, 046, 048, 049, 050, 051, 052, 059, 060, 061 and 062 for the month of **September 2008**. Submission of DMR data is a requirement of your NPDES permit (Part II, Item 4 – Reporting), even if the facility is not operating.

Be advised that failure to satisfy the reporting requirements of your NPDES permit may be cause for enforcement action pursuant to the Ohio Revised Code Chapter 6111.

Please submit the above referenced DMR within ten business days of the date on this letter if you have not already done so. If there are any questions, please contact me at (740) 380-5206.

Sincerely,

Jennifer M. Witte
Chemical Engineer - Environmental Specialist II
Division of Surface Water

JMW/dh