



State of Ohio Environmental



Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

May 26, 2010

RE: CARROLL COUNTY
VILLAGE OF MALVERN WATER
COMMUNITY WATER SYSTEM
PWS ID. NO. 1000112
STU ID. NO. 1053068

Mr. James Bates
Water Plant Superintendent & Village Administrator
Village of Malvern, Water Plant
P.O. Box 844
410 North Carrollton Road
Malvern, OH 44644

NOTICE of VIOLATION

Dear Superintendent Bates:

This office has reviewed the monthly operating reports for April 2010. The results indicate that on two occasions, an exceedance of the secondary maximum contaminant level (MCL) for manganese occurred. Details of these exceedances included:

<u>Date</u>	<u>Contaminant</u>	<u>Level milligrams/Liter (mg/L)</u>
April 6, 2010	Manganese	0.076
April 12, 2010	Manganese	0.061

The Ohio Administrative Code (OAC) Rule 3745-82-02 has set the secondary MCL for manganese at 0.05 mg/L. Be advised that the listed results are above the secondary MCL for manganese.

A letter dated April 20, 2010, from you documented the exceedance on April 6, 2010 was because of a solenoid valve equipment malfunction. This office is requesting you provide an explanation of why the second exceedance occurred and the corrective action(s) you are taking to avoid these exceedances in the future. Submit your response to this office within thirty days of the date of this letter.

Sincerely,

Cynthia M. Petretich
Cynthia M. Petretich
Environmental Specialist
Division of Drinking and Ground Waters

CMP:dms

pc: Dave Evans, DDAGW, CO
Kim Eters, DDAGW, NEDO
Carroll County Health Department
Dee Dee Wise, Water Plant Administrator

ec: Stivo DiFranco, Supervisor, DDAGW, NEDO