



State of Ohio Environmenta



Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

March 27, 2008

RE: **NOTICE OF VIOLATION**
SUMMIT COUNTY
COUNTRY VIEW SOUTH APARTMENTS
COMMUNITY WATER SYSTEM
PWS ID # OH7707512

Mr. Joel Helms
Country View South Apartments
4977 Massillon Rd.
North Canton, OH 44720

CERTIFIED MAIL

Dear Mr. Helms:

This letter is notification that the Country View South Apartments public water system is in violation of Ohio Administrative Code (OAC) Rule 3745-83-01 for failure to maintain a minimum of 0.2 mg/L free chlorine residual measured at representative points throughout the distribution system.

This violation of OAC is based on my site visit conducted on March 26, 2008. A resident in apartment #21B allowed me to check the free chlorine residual from the kitchen tap. After letting the water run for a few minutes, NO free chlorine residual was detected. Approximately ten minutes later, another free chlorine residual was collected from apartment #29A. The free chlorine residual was 0.09 mg/L. The minimum free chlorine residual in the distribution was less than 0.2 mg/L. Please be reminded that community public water systems must maintain a minimum of 0.2 mg/L free chlorine residual at all times.

An evaluation/investigation should be conducted to determine why the low residual occurred and what corrective action is necessary. Please provide your findings to this writer by April 25, 2008. Include with your findings a map that identifies the locations of the low residuals.

If you have any questions, please contact me directly at (330) 963-1248.

Respectfully,

J. Robert Henn
Environmental Specialist
Division of Drinking and Ground Waters

JRH/ams

cc: Toni Buchanan, Ohio EPA, Central Office, DDAGW