



State of Ohio Environmental
Northeast District



2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

January 23, 2008

RE: SUMMIT COUNTY
HUDSON ESTATES
COMMUNITY WATER SYSTEM
PWS ID # OH7702512
STU ID # OH7758617

Mr. Steve Hoake
Evergreen Manufactured Home Community, LLC
1518 N. Avon St.
Burbank, CA 91505

Dear Mr. Hoake:

Water samples collected weekly have been analyzed and evaluated for iron and manganese. The iron results exceeded the secondary maximum contaminant level (SMCL). Rule 3745-82-02 of the Ohio Administrative Code (OAC) has set the SMCL for iron at 0.03 mg/L.

The following table identifies those dates where the iron levels were over the SMCL for the month of December 2007:

DATE	IRON (SMCL OF 0.3 mg/L)
December 1	0.5
December 3	1.0
December 4	1.0
December 5	1.5
December 6	2.0
December 13	0.5

Please investigate the cause of the iron spikes. Please send documentation back to this writer within 45 days from receipt of this letter indicating what steps have been taken to ensure that iron and/or manganese level(s) are below the SMCL.

Please contact me at (330) 963-1248, if you have any questions.

Sincerely,

J. Robert Henn, Environmental Specialist
Division of Drinking and Ground Waters

cc: Dennis Taber

JRH/ams