



State of Ohio Environmental



Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

October 10, 2007

RE: CARROLL COUNTY
MOHAWK UTILITIES, INC.
COMMUNITY WATER SYSTEM
PWS ID # OH1000812
STU ID #1053070 (Plant No. 1)

Mr. Jon Robertson, Superintendent
Mohawk Utilities, Inc.
7326 Canton Road, NW
P.O. Box 566
Malvern, Ohio 44644

NOTICE OF VIOLATION

Dear Mr. Robertson:

This office has reviewed the monthly operating reports for August 2007. The results indicate that on three occasions, an exceedance of the secondary Maximum Contaminant Level (MCL) for manganese occurred at STU ID No. 1053070 (Plant No. 1). These exceedances included:

<u>Date</u>	<u>Contaminant</u>	<u>Level (milligrams/Liter) (mg/L)</u>
August 8, 2007	Manganese	0.062
August 14, 2007	Manganese	0.058
August 24, 2007	Manganese	0.061

The Ohio Administrative Code (OAC) Rule 3745-82-02 has set the secondary MCL for manganese at 0.05 mg/L. Be advised that the listed results are above the secondary MCL for manganese. This office is requesting you provide an explanation of why the exceedances occurred. Submit your response to this office within 30 days of the date of this letter.

Sincerely,

Cynthia M. Petretich
Environmental Specialist
Division of Drinking and Ground Waters

CMP/ams

cc: Dave Evans, Ohio EPA, Central Office, DDAGW
Nancy Glenny, Ohio EPA, NEDO, DDAGW
Cliff Evans, PUCO

ec: Stivo Di Franco, Ohio EPA, NEDO, DDAGW