



State of Ohio Environmen

Northeast Dist.



* 0 H 1 0 0 0 8 1 2 3 1 2 0 0 7 N O V *

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

March 1, 2007

RE: CARROLL COUNTY
MOHAWK UTILITIES, INC.
COMMUNITY WATER SYSTEM
PWS ID. NO. 1000812
STU ID. NO. 1053070 (Plant No. 1)

Mr. Jon Robertson, Superintendent
Mohawk Utilities, Inc.
7326 Canton Road, NW
P.O. Box 566
Malvern, Ohio 44644

NOTICE OF VIOLATION

Dear Mr. Robertson:

This office has reviewed the monthly operating reports for January 2007. The results indicate that on one occasion, an exceedance of the secondary Maximum Contaminant Level (MCL) for manganese occurred at STU ID No. 1053070 (Plant No. 1). This exceedance included:

<u>Date</u>	<u>Contaminant</u>	<u>Level milligrams/Liter (mg/L)</u>
January 19, 2007	Manganese	0.191

The Ohio Administrative Code (OAC) Rule 3745-82-02 has set the secondary MCL for manganese at 0.05 mg/L. Be advised that the listed result is above the secondary MCL for manganese. This office is requesting you provide an explanation of why the exceedance occurred. Submit your response to this office within 30 days of the date of this letter.

Sincerely,

Cynthia M. Petretich
Environmental Specialist
Division of Drinking and Ground Waters

CMP/ams

cc: Dave Evans, Ohio EPA, Central Office, DDAGW
Nancy Glenny, Ohio EPA, NEDO, DDAGW

ec: Stivo Di Franco, Supervisor, Ohio EPA, NEDO, DDAGW

