



State of Ohio Environment



Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

February 26, 2007

RE: WAYNE COUNTY  
HERITAGE GREEN CONDOMINIUMS -  
KIDRON  
COMMUNITY WATER SYSTEM  
PWS ID # 8562512  
STU ID # 8561747

Mr. Roger Geiser  
Heritage Green Condominium Association  
106 Heritage Green Lane  
Dalton, OH 44618

Dear Mr. Geiser:

On February 9, 2007, this office received the January 2007 Monthly Operating Report (MOR form 5002) from the Heritage Green Condominium Association. The MOR is provided as a means to relay compliance information about the operation of the water treatment plant. Operational monitoring is conducted throughout the month to test the treatment effectiveness of the water plant. Since Heritage Green Condominium Association treats its water by potassium permanganate injection for manganese green sand filtration (iron and manganese removal), and chlorine injection (disinfection), you are required to conduct monitoring for iron, manganese, and chlorine residual.

Please note the following violations:

1. At least one sample each month for iron and manganese is required to be analyzed by a certified laboratory. In accordance with Ohio Administrative Code (OAC) 3745-82-02, plant tap iron levels must remain at or below the secondary maximum contaminant level (MCL) of 0.3 milligram per liter (mg/L) at all times. Plant tap manganese levels must remain at or below the secondary MCL of 0.05 mg/L at all times.

On the January 2007 MOR, the iron and manganese levels were NOT reported. Please submit a copy of your January 2007 iron and manganese sampling results to this office within 10 days of receipt of this letter.

2. OAC Section 3745-83-01 requires all community and major non-community water systems to maintain a minimum chlorine residual of at least 0.2 mg/L free chlorine, or 1.0 mg/L combined chlorine, measured at representative points throughout the

HERITAGE GREEN CONDOMINIUMS - KIDRON  
FEBRUARY 26, 2007  
PAGE 2

residuals were reported as less than 0.2 mg/L free chlorine, or 1.0 mg/L combined chlorine. Please adjust your chlorine injection treatment to ensure distribution free chlorine always remains above 0.2 mg/L free chlorine, or 1.0 mg/L combined chlorine, at all times.

If you have any questions regarding this correspondence, or if you need any assistance, please contact me at (330) 963-1194 or at my e-mail address, [beth.madis@epa.state.oh.us](mailto:beth.madis@epa.state.oh.us).

Sincerely,



Beth R. Madis  
Environmental Specialist  
Division of Drinking and Ground Waters

BRM/ams

cc: Wayne County Health Department  
Dave Evans, Ohio EPA, Central Office, DDAGW  
Wayne Leichy, Heritage Green Condominium Association  
Ray Steiner, Heritage Green Condominium Association  
Rick Jackson