



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

February 21, 2013

Certified Mail

Mr. William Beam
P.O. Box 78
206 Main Street
Port William, Ohio 45164

Warning Letter

**RE: Fugitive Dust Concerns and Air Pollution Permit Requirements for MWB
Family Limited Partnership, 206 Main St., Port William, Ohio 45164**

Dear Mr. Beam:

Thank you for all of your cooperation and assistance during my February 20, 2013, fugitive dust complaint investigation and the steps that you are willing to take to minimize and/or eliminate the release of fugitive dust from your Port William facility.

The purpose of this letter is to request that MWB:

- **Continue proactive steps to minimize and/or eliminate fugitive dust from being emitted from the Port William facility; and**
- **Apply for and obtain air pollution permits.**

Proactive Steps to Minimize and/or Eliminate Fugitive Dust Emissions:

During the investigation, we discussed your operations and areas of possible fugitive dust emissions. The periodic watering of the plant and local roadways is very effective at reducing the release of fugitive dust related to vehicle and truck traffic throughout the facility. However, during my investigation I noticed that the surface material on the roadways and plant surface areas has been ground to a fine powder in areas. Please review the facility and submit a report to this office outlining additional steps that are planned or have been taken to minimize and/or eliminate the release of fugitive dust emissions.

Mr. William Beam
MWB
February 21, 2013
Page 2

Apply for and Obtain Air Pollution Permits:

During the discussion, you mentioned that MWB is a long term grain storage terminal under contract with Cargill. Ohio Administrative Code (OAC) rule 3745-31-02(A)(1)(b), requires that no person shall cause the installation of any new source, without first obtaining a Permit to Install and Operate (PTIO). Based on a review of the Ohio EPA database, there are no air pollution permits covering MWB operations in Port William.

This office requests that MWB complete and submit a PTIO Application and Emissions Activity Category (EAC) forms to this office to cover the operations at 206 Main St., Port William, Ohio, 45164. I have attached the following forms to this letter: PTIO Application Sections I and II; EPA Form 3111, EAC Form Roadways and Parking Areas; EPA Form 3101, EAC Form Fuel Burning Operations; and EPA Form 3120/3121, EAC Form Grain Terminals and Elevators. These forms can also be found online at <http://www.epa.ohio.gov/dapc/fops/eac/eacforms.aspx>.

Please be aware that the Ohio EPA now has an e-business service that allows you to submit your air pollution application and other forms electronically online at <https://ebiz.epa.ohio.gov/login.jsp>. For assistance setting up an ebiz account, you can follow the instructions at our ebiz login site or go to <http://epa.ohio.gov/dapc/airservices.aspx>. Assistance in filling out the PTIO Application and EAC forms can be obtained at: http://www.epa.ohio.gov/dir/permit_assistance.aspx; contacting Mr. Jim Pellegrino, Office of Compliance Assistance and Pollution Prevention (OCAPP) at (937) 285-6439, and/or me at (937) 285-6063.

Please submit the above information to this office by April 5, 2013.

If you have any questions or concerns about the above information, please feel free to contact me at (937)285-6032.

Sincerely,



Terry A. Sanner
Environmental Specialist
Division of Air Pollution Control

TS/kb

Enclosure

ec: Jim Pellegrino, SWDO/OCAPP
John Paulian, CO/DAPC
Tom Schneider, SWDO/DAPC

7005 2570 0001 6229 3465

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com®

OFFICIAL USE

Postage	\$
Certified Fee	
Return Receipt Fee (Endorsement Required)	
Restricted Delivery Fee (Endorsement Required)	
Total Postage & Fees	\$

Postmark Here

Sent To

MR. WILLIAM BEAM
P.O. BOX 78
206 MAIN STREET
PORT WILLIAM, OHIO 45164

Street, Apt. No., or PO Box No.
City, State, ZIP+4

PS Form 3800, June 2002 See Reverse for Instructions

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

MR. WILLIAM BEAM
P.O. BOX 78
206 MAIN STREET
PORT WILLIAM, OHIO 45164

COMPLETE THIS SECTION ON DELIVERY

A. Signature
 Mr. William Beam Agent
 Addressee

B. Received by (Printed Name) C. Date of Delivery

D. Is delivery address different from item 1? Yes
If YES, enter delivery address below: No

3. Service Type
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

2. Article Number (Transfer from service label) **7005 2570 0001 6229 3465**