



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

February 23, 2012

Jamie Mallow  
2101 Kenskill Avenue  
Washington Court House, OH 43160

**Re: Sugar Creek Packing Company, Fayette County  
Industrial Storm Water Permit 4GR00458\*DG**

Dear Mr. Mallow:

This letter is written in regard to an industrial storm water inspection that I conducted at Sugar Creek Packing Company, on February 17, 2012, at your facility located at 2101 Kenskill Avenue, in Washington Court House, Ohio. The inspection was conducted in order to determine compliance with your industrial storm water general permit. Your facility processes poultry-based foods. Overall, the facility was adhering to the general permit, but will need better housekeeping in some areas. The following items were noted during the inspection, also please see attached pictures:

Your storm water pollution prevention plan (SWP3) was up to date but will need to be updated in the near future. Please update your storm water pollution prevention plan (SWP3) and send me an electronic copy to [greg.sanders@epa.ohio.gov](mailto:greg.sanders@epa.ohio.gov). Please be aware that the SWP3 should be reviewed annually or after a change in management.

I noted oil staining near the tractor trailer storage area. Please provide spill kits near this area and instruct employees to use them after spills. Please see attached pictures.

There needs to be better housekeeping near the fats and grease unloading containment area. Grease is being tracked outside of the containment area. Please see attached pictures.

Empty drums and/or totes were stored upright and with lids per the permit conditions. Full or partially full drums and/or totes were stored in secondary containment per the permit conditions.

Please store the inedible fats garbage cans inside the building. I understand that there were some staffing issues during my inspection which led to the garbage cans being stored outside. Please see attached pictures.

There was a storm water drain on the east side of the facility that was collecting a lot of pollutants and sediment. Please use better housekeeping measures to prevent the discharge of pollutants and/or sediment to the storm water drains. Please see attached pictures.

There needs to be better housekeeping near the enclosed dumpsters. Most likely the debris came from the changing of the dumpsters. Revise the SWP3 to include best management practices to prevent the accumulation of debris around the enclosed dumpsters.

Jamie Mallow  
Page -2-

It was discussed during the inspection that your company recently purchased the TI Automotive building and property adjacent to your property. You stated that this may become cold storage for your company. Please include this property in your revised SWP3.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3851.

Sincerely,

A handwritten signature in black ink, appearing to read 'G.L.S.', written in a cursive style.

Gregory L. Sanders  
Environmental Specialist  
Division of Surface Water  
Central District Office

cc: John Woodrow, City of Washington CH WWTP

ec: Greg Sanders, DSW/CDO

GS/nsm Sugar Creek Packing, February 17, 2012



