



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 05, 2012

Mike Haughton
Rolls Royce Energy Systems Inc.
105 North Sandusky Street
Mount Vernon, OH 43050

**Re: Storm Water Inspection at Rolls Royce Energy Systems Inc.
Permit Number: 4GC03814*AG**

Dear Mr. Haughton:

This letter is written in follow-up to a construction storm water inspection by Alicia Rector and Abigail Tamkin of the Ohio EPA, at Rolls Royce Energy Systems Inc located at 105 North Sandusky Street in Knox County on June 28, 2012. The purpose of the inspection was to evaluate compliance with Ohio EPA's General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

Sediment and Erosion Controls:

- The silt fence on the western portion of the site is not properly entrenched and will require maintenance (See Photo Figure 1).

Post Construction Requirements:

- The General Storm Water Permit requires specific post construction water quality treatment for all sites. Guidance regarding the post construction requirements is found at: <http://www.epa.state.oh.us/dsw/storm/CGPPCQA.aspx>. Please submit to my attention (email preferred at harry.kallipolitis@epa.state.oh.us) which practice will be installed at this site to ensure compliance with the General Permit. Please include all design criteria and calculations in your submission.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Rolls Royce Energy Systems Inc. 6-28-2




Figure 1: silt fence not entrenched properly