



**Environmental
Protection Agency**

John R. Kasich, Governor

Mary Taylor, Lt. Governor

Scott J. Nally, Director

July 12, 2012

RE: CUYAHOGA COUNTY
CLEVELAND
INDUSTRIAL STORM WATER
MORRISON PRODUCTS, INC.
PERMIT NO: 3GR01232

Mr. Ron Kinkade
Training Manager
Morrison Products, Inc.
16900 South Waterloo Road
Cleveland, OH 44110

Dear Mr. Kinkade:

On July 10, 2012, this writer conducted an inspection of your facility, located at 16900 South Waterloo Road, Cleveland, Ohio to determine compliance with the Ohio EPA General Storm Water National Pollutant Discharge Elimination System (NPDES) Permit for Industrial Activity. As a representative of Morrison Products, Incorporated, you were present during the inspection as well. Along with my observations from the inspection, I have provided comments concerning your permit below:

General

1. This site is the location of Morrison Products, Incorporated, a facility that manufactures sheet metal fabrications for HVAC components.
2. The facility is unsure where exactly the storm drains discharge to. There is one trench drain inside the building.

Inspection Observations

1. The waste compactor is uncovered. The compactor must be covered with a lid or tarp to prevent the collection of storm water and the formation of leachates.
2. There were a few oil stains in the east loading dock area. Implement good housekeeping practices to make sure when a spill or leak is identified, it is cleaned up immediately and a drip pan is placed under the leak.
3. There is no spill kit near the loading dock inside the building. In case of a spill, a spill kit must be located in the area and clearly identified.

Permit

1. The site map in your Storm Water Pollution Prevention Plan (SWPPP) does not show the underground drainage of your storm water system. As required in Part 5.1.2 of the NPDES permit, the site map must show the locations of all storm water conveyances including ditches, pipes and swales.

Action Items


- Cover waste compactor with lid or tarp.
- Place a spill kit, clearly labeled, near the inside loading dock area.
- Implement good housekeeping practices throughout the facility.
- Make aforementioned improvements to site map in SWPPP.

MORRISON PRODUCTS, INC.
JULY 12, 2012
PAGE 2 OF 2

You are directed to provide me with a letter of response, no later than July 25, 2012, indicating the actions you will take to address the concerns and violations noted above.

If you should have any questions concerning this letter, feel free to contact me at (330) 963-1128 or by e-mail robert.hrusovsky@epa.state.oh.us.

Sincerely,

A handwritten signature in black ink, appearing to read "Robert Hrusovsky", with a long, sweeping flourish extending to the right.

Robert Hrusovsky
Assistant to the District Engineer
Division of Surface Water

RH/cs

cc: Rachid Zoghaib, Commissioner, Division of Water Pollution Control, City of Cleveland