



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

July 11, 2012

Tucker Bohm  
Daimler Group  
1533 Lake Shore Drive  
Columbus, Ohio 43204

**Re: Storm Water Inspection at Franklin County Children Services- Franklin County  
Permit # 4GC03725\*AG**

Dear Mr. Bohm:

This letter is written in follow-up to a construction storm water inspection by Brittany Turner, Abigail Tamkin, and Kathryn Rumora of the Ohio EPA, at Franklin County Children Services located at 4071 E. Main Street, Whitehall, Ohio on July 5, 2012. The purpose of the inspection was to evaluate compliance with Ohio EPA General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

**Sediment and Erosion Controls:**

- Corrective measures are expected to provide a containment structure for all concrete wash-out. (Figure 1, 2, 3, & 4)
- Concrete batching station must be contained. (Figure 5)
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days. (Figure 6).

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

HK/nsm Franklin county children Services Franklin County 7-6-2012

Central District Office  
50 West Town Street, Suite 700  
P.O. Box 1049  
Columbus, OH 43216-1049

614 | 728 3778  
614 | 728 3898 (fax)  
www.epa.ohio.gov



Figure 1 Proper containment required



Figure 2 Proper containment required



**Figure 3 Proper Containment Required**



**Figure 4 Proper containment required**



**Figure 5 Containment must be provided for concrete batching**



**Figure 6 Baron area**