



John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

January 3, 2013

John Wise or Current Storm Water Manager  
Target Corporation  
P.O. Box 111  
Minneapolis, MN 55440

**Re: Target at Reynoldsburg Permit Number 4GC02234\*AG**

Dear Mr. Wise:

This letter is written in follow up to my site observations of the post construction water quality treatment measures noted at the Target at Reynoldsburg in Reynoldsburg, Ohio on December 31, 2012.

It appears the water quality basin located on the west end of the property is **NOT** functioning as intended. It appears the outlet structure which is designed to discharge a water quality volume associated with a 0.75 inch rain event over a 48 hour period, is clogged.

As a result there are no provisions for treatment of the water quality volume as required by the Ohio EPA General Storm Water Permit. It is obvious that maintenance is required. Please respond within seven days from receipt of this letter regarding the corrective actions to address this issue.

Please ensure the forebays and micro pools are cleaned out as found necessary as the two act as a repository for accumulated sediments.

The outlet structure must be routinely inspected to ensure an appropriate working condition. In the event accumulated water in the basin remains in excess of 48 hours or is discharge prior to a 48 hour period following each significant rain event, it is evident there is a malfunction.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at 614-728-3844 or via email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely

Harry Kallipolitis  
Environmental Specialist  
Division of Surface Water  
Central District Office

HK/nsm Target at Reynoldsburg