



10 years and moving forward

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Cathy J. Kelly, Director

March 6, 2013

Jonathan Saunders
Burton Metal Finishing Inc.
1711 Woodland Avenue,
Columbus, Ohio 43219

**Re: Industrial Storm Water Inspection at Burton Metal Finishing Inc.
Permit Number 4GR000167*EG**

Dear Mr. Saunders:

This letter is written regarding our joint storm water inspection we conducted at Burton Metal Finishing located at 1711 Woodland Avenue, Columbus, Ohio on February 26, 2013. Mike Smith with Burton Metal Finishing was present at this inspection. The purpose of the inspection was to evaluate compliance with the Multi Sector General Storm Water Permit (MSGP) associated with Industrial Activities found at http://www.epa.ohio.gov/dsw/permits/GP_IndustrialStormWater.aspx. The following items were noted:

Storm Water Pollution Prevention Plan (SWPPP):

- The SWPPP was updated to reflect the new conditions of the Multi Sector General Storm Water Permit. The specific sector requirements were included. Please be sure to evaluate and update the MSGP as significant changes in operations or Best Management Practices (BMP) implementation are noted.

Site Observations:

- The secondary containment structure associated with the storage tank located at the rear of the facility is cracked and must be maintained to ensure the intended function. It did appear to be holding water at the time of the inspection, and I agreed to the repair of the secondary containment structure concurrent with more suitable weather conditions.

- I agreed to the alternative unloading procedures associated with the Hazardous Waste tanks located inside the facility. A new unloading area will be established on the west end of the building where all connections and transfer of material are conducted in an area which drains to pre-treatment. At this time, I am suggesting the new unloading protocols are implemented within six months from receipt of this letter.
- Please post the Ohio EPA Spill Hotline (800) 282-9378 in the chemical storage building.
- Please provide a pallet which provides secondary containment for the chemicals transported from the chemical storage building to the plant.
- During the inspection we agreed to the location of your monitoring outfalls for the facility, please be sure to update your SWPPP to reflect the new locations.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,



For HK

Harry Kallipolitis
Storm Water Coordinator
Central District Office
Division of Surface Water



Figure 1: Washing Activities outside washpad