



John R. Kasich, Governor
Richard Cordell, Lt. Governor
Scott J. Walby, Director

June 5, 2013

Ryan Riley
Columbia Gas of Ohio / NiSource Company
1600 Dublin Road
Columbus, Ohio 43215

Re: **Storm Water Inspection at Cline AMRP / Franklin County**
Permit Number: 4GC04037*AG

Dear Mr. Riley:

This letter is written in follow up to a construction storm water inspection by Brittany Turner of the Ohio EPA, at Cline AMRP located at Bounded by Stewart Avenue and Mithoff Street on May 31, 2013. The purpose of the inspection was to evaluate compliance with Ohio EPA's General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

Sediment and Erosion Controls

- The site is lacking inlet protections. Inlet protections are required provided the storm sewer system is not routed to an approved centralized sediment basin or demonstrate an acceptable alternative (See Figure 1).
- Please be aware that the General Permit indicates that all sediment controls will be inspected and maintained every seven days or within 24 hours of a precipitation event equal to or greater than 0.5 inches. A log of inspection must be maintained on site for the agency to review.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Cline AMRP 5-31-2013