



John E. Kasich, Governor
Mary Taylor, Lt. Governor
Scott B. Kally, Director

June 27, 2013

Bryan Kopachy
Columbia Gas of Ohio/ NiSource Co
3550 Johnny Appleseed Ct
Columbus, OH 43231

Re: Storm Water Inspection at Hosack Street/ South 4th Street Relocation/ Franklin County. Permit Number: 4GC04010*AG

Dear Mr. Kopachy:

This letter is written in follow-up to a construction storm water inspection by Jerome Hoke and Brittany Turner of the Ohio EPA, at Hosack Street/ South Fourth Street Relocation located at Welch Avenue to North, Merrit Street to South, Wager Street to East, and Pearl Street to West on June 13, 2013. The purpose of the inspection was to evaluate compliance with Ohio EPA's General Storm Water Permit Associated with Construction Activities. This was previously reported in a letter from May 22, 2013. During the inspection, we noted the following:

Sediment and Erosion Controls

- Sediment controls for this project must be implemented in accordance with the General Storm Water Permit. It appears that the inlet protections throughout the project have not been installed correctly, allowing for direct bypass of sediment laden waters to enter storm sewer system (see Fig. 1 and 2), specifically along Hosack Street. These will require reinstallation to ensure properly functioning condition or demonstrate an approvable alternative.

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/hsm Hosack St. 4th St. Relocation 6-13-13




Fig 1: Dandy bag requires reinstallation




Fig 2: Dandy bag requires proper maintenance and reinstallation