



John R. Kasich, Governor
Steve Ingler, Lt. Governor
Scott L. Raily, Director

July 10, 2013

Steve Lark
Nationwide Realty Investors
375 North Front Street, Suite 200
Columbus, OH 43215

Re: Construction Storm Water Inspection at Arena District Development Flats II / Franklin County, Permit Number: 4GC03956 *AG

Dear Mr. Lark:

This letter is written regarding a storm water inspection conducted by Sam Marotta and Rachel Bellis of the Ohio EPA, at the Arena District Development Flats II located at the east corner of Neil Avenue and Brodbelt Lane on June 26, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- Please maintain all perimeter controls to minimize sediment loss from the site. (See Figures 1 and 2).

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Arena District Development Flats II 6-26-13




Figure 1: Maintain Perimeter Controls