



John E. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Mealy, Director

September 10, 2013

Brent Wrightsel
Vision Development Company
3300 Riverside Drive #100
Columbus, Ohio 43221

**RE: Construction Storm Water Inspection at Edwards Farms Multifamily/ The District/
Franklin County, Permit Number: 4GC03985*AG**

Dear Mr. Wrightsel,

This letter is written regarding a storm water inspection conducted by Elizabeth Pleta and Jerome Hoke of the Ohio EPA at Edwards Farms Multifamily/ The District located at 5049 Edwards Farm Road on August 19, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- During the inspection, there was evidence of recent clearing activity on the northwest side of the site adjacent to stream (See Figure 1). Please ensure proper sediment controls are installed within three (3) days.
- It appeared the site lacked inlet protections. Please ensure that sediment controls are installed within three (3) days of receiving this letter.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely

Harry Kallipolitis
Storm Water Coordinator
Ohio EPA
Division of Surface Water

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO



Figure 1 Clearing activities adjacent to a stream on the northwest side of the site.