



City of Cleveland  
Frank G. Jackson, Mayor

Department of Public Health  
Division of Air Quality  
75 Erieview Plaza, Second Floor  
Cleveland, Ohio 44114-1839  
216/664-2297 • Fax: 216/420-8047  
www.clevelandhealth.org

**SERVING OHIO EPA AS AGENCY 13  
FOR CUYAHOGA COUNTY**

**CERTIFIED MAIL 7011 3500 0000 1759 8300  
RETURN RECEIPT REQUESTED**

June 3, 2013

Ricky D. Smith, Director  
Cleveland Hopkins International Airport  
5300 Riverside Drive  
P.O. Box 81009  
Cleveland, OH 44135

**HIGH PRIORITY FACILITY**

**FACILITY ID: 13-18-00-4181**

**NOTICE OF VIOLATION: Failure to perform and maintain daily visible emissions checks and daily ash removal logs on Emission Unit (EU) N001: Kelley Hoskins Incinerator**

Dear Mr. Smith:

On May 14, 2013, the Cleveland Division of Air Quality (CDAQ) inspected Cleveland Hopkins International Airport located at 19501 Five Points Road in Cleveland. This letter serves as notification that you are operating sources in violation of the following applicable air statutes, air regulations, or air permit conditions.

Cleveland Hopkins International Airport has failed to perform and maintain daily visible emissions checks and daily ash removal logs for Emission Unit (EU) N001: Kelley Hoskins Incinerator since Permit To Install and Operate (PTIO) # P0107053 was issued on March 8, 2011. This is a violation of Ohio Revised Code (ORC) Section 3704.05(C) and PTIO # P0107053 Parts C. 1. d. 1. and 4., respectively.

Unless you undertake some type of corrective action with respect to the above noted violations, you will remain in non-compliance. CDAQ requests that Cleveland Hopkins International Airport submit two weeks' worth of required records for daily visible emissions checks and daily ash removal logs for EU N001: Kelley Hoskins Incinerator to the following enforcement representative:

Andrew Marantides  
Cleveland Division of Air Quality  
75 Erieview Plaza 2<sup>nd</sup> Floor  
Cleveland, Ohio 44114-1839



CDAQ also requests that Cleveland Hopkins International Airport electronically submit, via the eBusiness Center, corrected Permit Evaluation Reports (PERs) for the reporting periods of April 1, 2010 to March 31, 2011, April 1, 2011 to March 31, 2012 and April 1, 2012 to March 31, 2013 to accurately reflect the monitoring and recordkeeping deviations on EU N001: Kelley Hoskins Incinerator.

Your written response to this letter must be received by CDAQ within thirty (30) days of your receipt of this letter. If there is insufficient time to correct the alleged violations within this timeframe, your response must include a timeline for correcting the alleged violations.

Violations of Ohio air pollution laws and /or permit terms and conditions are subject to the penalties stipulated in Ohio Revised Code Section 3704.99(A), which allows fines of not more than twenty-five thousand dollars (\$25,000) or imprisonment for not more than one year, or both, for each violation.

CDAQ issues this letter with Ohio EPA's concurrence. The failure to mention any specific violation does not excuse any violations of local, state and federal laws or regulations regarding air pollution control. Violations of air pollution control laws may be pursued in local court or referred to Ohio EPA or U.S. EPA for further enforcement action.

Should you have any questions, please call Andrew Marantides at (216) 420-8049. All correspondence with CDAQ must include the Ohio EPA facility identification number for Cleveland Hopkins International Airport: 13-18-00-4181.

Sincerely,

Valencia White  
Chief of Enforcement, CDAQ

VW/AM

cc: Kim McGreal, Cleveland Hopkins International Airport  
Sarah Buzas, CDAQ  
George P. Baker, CDAQ  
Michael J. Krzywicki, CDAQ  
John Paulian, Ohio EPA Central Office  
Brian Dickens, U.S. EPA Region V  
L:\Data\Facilities\1318004181\2013-5-14 NOV.docx