



PHASE 0 AD-HOC BARCODE SHEET

12/7/2011 8:26 AM

Department:



DAPC

Subdepartment:



DUNE>

Office Location:



LAA-ARAQMD

Media:



AIR

Doc Type:



NOV

Doc Subtype:



DAPC-Permit

Program:



DAPC-NON-TITLE V

County:



52 - MEDINA

Facility ID



1652000048

Facility Name:
(Optional)



SIMIC'S SERVICE INC (Auto Load)

Date:



12/5/2011

Record ID:
(Optional)



**AKRON REGIONAL
AIR QUALITY MANAGEMENT DISTRICT**

TELEPHONE: (330) 375-2480

FAX: (330) 375-2402

December 5th, 2011

Premise No: 1652000048

Mr. Srecko Simic
Simic's Service, Inc.
1321 Ridge Road
Hinckley, OH 44233

RE: NOTICE OF VIOLATION OF OAC RULE 3745-21-09 (DDD)

Dear Mr. Simic:

Your Gas Dispensing Facility (GDF) is in violation of **OAC rule 3745-21-09 (DDD)(2) which specifies Stage II testing requirements and its frequency**. This facility was scheduled for testing on or before **September 17th, 2011**. Your Stage II testing was not completed until **November 18th, 2011**.

Our Agency is in receipt of the November 18th, 2011, Stage II test results submitted by North Coast Vapor Recovery Service for Simic's Marathon gasoline dispensing facility located at 1321 Ridge Road in Hinckley.

Upon review, the test results are accepted as received and will be included in the operating file for this facility. However, acceptance of the information requested by this Agency does not constitute a waiver of this Agency's or the Ohio EPA's authority to seek civil penalties as provided in Section 3704.06 of the Ohio Revised Code. This Agency always has the option to reject or accept late submittals. The determination to pursue or decline such penalties will be made at a later date.

This facility will be inspected on an annual basis for compliance with the Stage II vapor recovery rule. It is required that you keep record keeping information at a readily available location for inspection. For this Agency, it is requested that you keep copies of the required information at each individual location where all employees can access them.

Full compliance testing, as conducted at this facility, must be performed again within five year intervals according to the testing requirements of OAC rule 3745-21-09 (DDD)(2)(a)&(b). This facility will be due for **full testing** on or before **September 17th, 2015**. Notification of testing is required as before, as well as reporting requirements.

Thank you for your cooperation and assistance in this matter. If you have any questions, please contact me at 330/375-2480 ext 3354

Sincerely,



Harry J. Eckert
Environmental Specialist

HJE