



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

April 1, 2008

RE: RETURN TO COMPLIANCE  
FAILED ANNUAL STAGE II COMPLIANCE TEST  
BP #22336  
OHIO EPA ID #0247120954

CERTIFIED MAIL

Denise Lees  
BP Products North America  
PO Box 6038  
Artesia, CA 90702

Dear Ms. Lees:

The annual Stage II compliance test RETEST conducted at BP #22336 located at 5219 Detroit Rd. in Sheffield, Ohio 44035 on March 12, 2008, failed to demonstrated compliance with the requirements of Ohio Administrative Code Rule 3745-21-09 (DDD).

The next Stage II compliance test is due in February 2009.

If you have any questions regarding this letter, please do not hesitate to contact me at (330) 963-1223.

Sincerely,

Dennis Bush  
Environmental Manager  
Division of Air Pollution Control

DB:bo

cc: Bob Prinic, DAPC, NEDO  
Tom Kalman, DAPC, CO  
Lisa Holscher, USEPA, Region V  
Station Manager