



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korieski, Director

October 28, 2009

RE: WARNING LETTER
DEESEE OIL CORP.
DAPC FACILITY ID 0228000205

CERTIFIED MAIL

Salem Jaffal
DeeSee Oil Corp.
12411 Kinsman Rd.
Burton, OH 44021

Dear Mr. Jaffal:

Our records indicate that the last Stage II compliance demonstration at DeeSee Oil Corp. located at 12411 Kinsman Rd., in Burton was December 21, 2007. The compliance tests are required annually pursuant to Ohio Administrative Code (OAC) Rule 3745-21-09(DDD).

Failure to perform these required tests annually constitutes a violation of OAC Rule 3745-21-09(DDD). I am including a copy of the Rule as well as a list of testing companies for your convenience.

Please schedule any necessary repairs and conduct a retest **within 30 days of your receipt of this letter.**

The submission of the requested information does not constitute a waiver of Ohio EPA's authority to seek civil penalties as provided in ORC 3704.06. Ohio EPA will decide whether to pursue or decline to pursue penalties regarding this matter at a later date.

If you have any questions regarding this letter, please do not hesitate to contact me at (330) 963-1270.

Sincerely,

Tim Fischer
Environmental Supervisor
Division of Air Pollution Control

TF:bo

enclosures: OAC Rule 3745-21-09 (DDD)
List of Stage II testing companies