



State of Ohio Environmental Protection Agency

**Northeast District Office**

2110 East Aurora Road  
Twinsburg, OH 44087-1924

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Laura H. Powell, Acting Director

January 25, 2007

RE: NOTICE OF VIOLATION  
FAILURE TO CONDUCT ANNUAL STAGE II  
COMPLIANCE TESTING  
DAPC FACILITY ID #0204010448

**CERTIFIED MAIL**

Tony Continenza  
Saybrook Sunoco  
29200 Euclid Ave.  
Wickliffe, Ohio 44092

Dear Mr. Continenza:

Our records indicate that Saybrook Sunoco, located at 4964 North Ridge West in Ashtabula, Ohio, did not conduct the required annual Stage II compliance testing in calendar year 2006. The most recent Stage II testing was conducted on March 11, 2005.

Ohio Administrative Code (OAC) Rule 3745-21-09 (DDD) requires testing of the Stage II vapor control equipment annually for static leak and air to liquid ratio, as well as every five years for dynamic pressure. A copy of the rule is attached. We have also attached a listing of testing companies that routinely conduct Stage II tests in Ohio. Please contact one of them to arrange for testing before February 28, 2007.

We strongly advise that you conduct maintenance on your Stage II vapor control equipment prior to having the testing conducted. Also, be sure to have all of the records required by paragraph 3 of the above-mentioned rule available for inspection during the test.

If you have any questions, please do not hesitate to contact me at (330) 963-1223.

Sincerely,

Dennis Bush  
Environmental Manager  
Division of Air Pollution Control

DB:bo

enclosures