



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

June 4, 2007

CERTIFIED MAIL

02 47 00 0760

Ms. Elena Goodhall
BFI- Lorain County Landfill
43502 Oberlin-Elyria Road
Oberlin, Ohio 44074

RE: Notice of Violation - Failed stack test - Lorain 1 flare

Dear Ms. Goodhall:

On December 13 & 14, 2006, BFI had the Lorain 1 enclosed flare stack tested. The purpose of the stack test was to demonstrate compliance with the pollution limitations pursuant to permit-to-install (PTI) number 02-17601. Air Quality Specialist, Inc. (AQS) performed the stack test for BFI. On January 31, 2007, Ohio EPA received the stack test report. This letter is notifying you that the flare failed the stack test for hydrogen chloride (HCl).

Pursuant to PTI No. 02-17601, Lorain 1 has an allowable emissions limitation for HCl of 0.03 pounds per hour (lb/hr). The stack test results indicate that the Lorain 1 flare is emitting 0.26 lb/hr HCl, which is in excess of the permit allowable.

Within thirty (30) days of receiving this letter, please provide a schedule by which BFI intends to return the Lorain 1 flare to compliance.

If you have any questions, please do not hesitate to call me at 330-963-1258.

Sincerely,

Joseph C. Loucek, III
Environmental Specialist
Division of Air Pollution Control

JCL:bo

cc: Bob Princic, DAPC, NEDO
Dennis Bush, DAPC, NEDO
Tom Kalman, DAPC, CO
Lisa Holscher, USEPA, Region V