



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

May 29, 2007

RE: NOTICE OF VIOLATION  
FAILED ANNUAL STAGE II COMPLIANCE TEST  
SPEEDWAY/SUPERAMERICA #3060  
OHIO EPA ID #0243181141

CERTIFIED MAIL

Missy Stanaway  
Speedway/SuperAmerica LLC  
PO Box 1500  
Springfield, OH 45501

Dear Ms. Stanaway:

The annual Stage II compliance test conducted at Speedway/SuperAmerica #3060 located at 31000 Vine St. in Willowick, Ohio 44095 on May 18, 2007, failed to demonstrate compliance for the following parameters:

<u>Parameter</u>	<u>Pass/Fail</u>
A/L Test	Failed
Pressure Decay Test	Passed
Dynamic Pressure Test	Not required this year
Ohio EPA Inspection	Passed

The A/L test failed for dispensers #5 & #6 due to low vacuum. According to our records, this station also failed the A/L test in 2006. Please undertake better preventive maintenance for this site.

Please have the necessary repairs completed and the failing equipment retested within three weeks of your receipt of this letter.

Failed test results constitute a violation of OAC Rule 3745-21-09 (DDD).

Violation of state air pollution control regulations are punishable by a civil penalty of \$25,000 per violation. Issuance of this notice does not excuse any violation of state law regarding air pollution.

Sincerely,

Dennis Bush  
Environmental Manager  
Division of Air Pollution Control

DB:bo

cc: Bob Princic, DAPC, NEDO  
Tom Kalman, DAPC, CO  
Lisa Holscher, USEPA, Region V  
Station Manager