



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

June 5, 2007

RE: NOTICE OF VIOLATION
FAILED ANNUAL STAGE II COMPLIANCE TEST
SPEEDWAY/SUPERAMERICA #3690
OHIO EPA ID #0247130679

CERTIFIED MAIL

Missy Stanaway
Speedway/SuperAmerica LLC
PO Box 1500
Springfield, OH 45501

Dear Ms. Stanaway:

The annual Stage II compliance test conducted at Speedway/SuperAmerica #3690 located at 4208 East Lake Rd. in Sheffield Lake, Ohio 44054 on May 21, 2007, failed to demonstrate compliance for the following parameters:

<u>Parameter</u>	<u>Pass/Fail</u>
A/L Test	Failed
Pressure Decay Test	Failed
Dynamic Pressure Test	Not required this year
Ohio EPA Inspection	Passed

Please have the necessary repairs completed and the failing equipment retested within three weeks of your receipt of this letter. This is the second consecutive year that this site failed the dynamic pressure (static leak) test. Better preventative maintenance is needed at this site to prevent failing future tests.

Failed test results constitute a violation of OAC Rule 3745-21-09 (DDD).

Violation of state air pollution control regulations are punishable by a civil penalty of \$25,000 per violation. Issuance of this notice does not excuse any violation of state law regarding air pollution.

Sincerely,

Dennis Bush
Environmental Manager
Division of Air Pollution Control

DB:bo

cc: Bob Prinic, DACP, NEDO
Tom Kalman, DAPC, CO
Lisa Holscher, USEPA, Region V
Station Manager