



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

July 17, 2008

RE: NOTICE OF VIOLATION
FAILED ANNUAL STAGE II COMPLIANCE TEST
SPEEDWAY/SUPERAMERICA #9975
OHIO EPA ID #0247010863

Missy Stanaway
Speedway/SuperAmerica LLC
P.O. Box 1500
207 Walter St.
Springfield, OH 45501

CERTIFIED MAIL

Dear Ms. Stanaway:

The annual Stage II compliance test conducted at Speedway/SuperAmerica #9975 located at 712 N. Leavitt Rd. in Amherst, Ohio 44001 on July 15, 2008, failed to demonstrate compliance for the following parameters:

<u>Parameter</u>	<u>Pass/Fail</u>
A/L Test	Passed
Static Leak Test	Failed
Dynamic Pressure Test	Not required this year
Ohio EPA Inspection	Passed

Please schedule repairs and conduct a retest within 14 days of your receipt of this letter.

Failed test results constitute a violation of OAC Rule 3745-21-09 (DDD).

Violations of state air pollution control regulations are punishable by a civil penalty of \$25,000 per violation. Issuance of this notice does not excuse any violation of state law regarding air pollution. An enforcement action will be initiated if this site does not return to compliance within 14 days of your receipt of this letter.

Sincerely,

Dennis Bush
Environmental Manager
Division of Air Pollution Control

DB:bo

cc: Bob Princic, DAPC, NEDO
Tom Kalman, DAPC, CO
Lisa Holscher, USEPA, Region V
Station Manager

