



City of Cleveland
Frank G. Jackson, Mayor

Department of Public Health
Division of Air Quality
75 Erievue Plaza, Suite 200
Cleveland, Ohio 44114-1839
216/654-2297 • Fax: 216/420-8047
www.clevelandhealth.org

**SERVING OHIO EPA AS AGENCY 13
FOR CUYAHOGA COUNTY**

**CERTIFIED MAIL 7009 3410 0002 1934 1134
RETURN RECEIPT REQUESTED**

January 11, 2011

Bonnetta DuBreuil
Meriam Process Technologies
4801 West 150th Street
Cleveland, OH 44135

NON-HPV

FACILITY ID: 13-18-00-0839

NOTICE OF VIOLATION / FOLLOW-UP LETTER: Failure to submit application to operate an air contaminant source

Dear Ms. DuBreuil:

On December 28, 2010, the Cleveland Division of Air Quality (CDAQ) inspected Meriam Process Technologies (Meriam) located at 10920 Madison Avenue in Cleveland. This letter serves as notification that Meriam was operating sources in violation of the following applicable air statutes, air regulations, or air permit conditions.

It was determined from the inspection that Meriam was operating in violation of Ohio Administrative Code (OAC) rule 3745-31-02(A)(1)(b) and Ohio Revised Code (ORC) sections 3704.05(F) and (G), in that a renewal application for the operation of emissions unit N001: Donley Multi-Chamber Incinerator - 200 lbs/hr (0.45 MMBtu/hr), was not received by CDAQ. A permit-to-operate for this source had expired on September 1, 1997, and CDAQ had not received a renewal application for the continued operation of N001. Information provided during the inspection concluded that N001 was still used approximately twice a year. However, subsequent to the inspection, Meriam provided written documentation that N001 would be permanently taken out of service as soon as possible, and that a disposal company would be retained to properly dispose of used paint filters.

Additionally, Meriam had been operating in violation of City of Cleveland Codified Ordinances 259.01 and 263.01, in that Meriam failed to obtain City of Cleveland permits-to-operate by submitting City of Cleveland Air Contaminant fees for the following calendar years: 2006, 2007, and 2008. However, CDAQ is in receipt of the outstanding City of Cleveland Air Contaminant fees as of January 5, 2011.



CDAQ received a timely corrective action and appropriate steps were taken to bring each air emission source into compliance. CDAQ has determined that no further action is warranted at this time, but reserves its right to take such action in the future if necessary.

CDAQ issues this letter with Ohio EPA's concurrence. The failure to mention any specific violation does not excuse any violations of local, state and federal laws or regulations regarding air pollution control. Violations of air pollution control laws may be pursued in local court or referred to Ohio EPA or U.S. EPA for further enforcement action. Should you have any questions, please call Valerie Shaffer at (216) 664-6292. All correspondence with CDAQ must include the Ohio EPA facility identification number for Meriam: 13-18-00-0839.

Sincerely,

Linda Jimmy for G.B.
George Baker
Chief of Enforcement

GB/vls

cc: Michael J. Krzywicki, CDAQ
John Paulian, Ohio EPA Central Office
William MacDowell, U.S. EPA Region V
Facility File and L:\Data\Facilities\1318000839\2010-12-28 NOV+NEAR.docx

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

Adalot / Meriam Process
Tech.
Attn: Bonnetta DuBrew
4801 W. 150th St.
Cleveland, OH 44135

COMPLETE THIS SECTION ON DELIVERY

A. Signature Agent
 J. Brewer Addressee

B. Received by (Printed Name) C. Date of Delivery
J. Brewer *XII 18*

D. Is delivery address different from item 1? Yes
If YES, enter delivery address below: No

3. Service Type
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

2. Article Number
(Transfer from service label) 7009 3410 0002 1934 1134