

SERVING OHIO EPA AS AGENCY 13
FOR CUYAHOGA COUNTY

CERTIFIED MAIL #70022030000118087995
RETURN RECEIPT REQUESTED

July 20, 2009

Rodney Wilson
Wilson and Sons Incorporated
34180 Chagrin Blvd
Moreland Hills, 44022

EMISSIONS VIOLATION

FACILITY ID: 13-18-35-6236

NOTICE OF VIOLATION : Failing to control emissions of volatile organic compounds from a stationary source

Dear Mr. Wilson:

On July 20, 2009, the Cleveland Division of Air Quality (CDAQ) inspected Wilson and Sons Incorporated located at 34180 Chagrin Blvd in Moreland Hills. This letter serves as notification that you are operating sources in violation of the following applicable air statutes, air regulations, or air permit conditions.

On July 20, 2009, CDAQ found a pressure valve on a vapor recovery tube was depressed, with no pressure on the seal. This is a violation Ohio Administrative Code Rule 3745-21-09 DDD(1)(b)(ix).

Unless you undertake some type of corrective action with respect to the above noted violations, you will remain in non-compliance. CDAQ requests that Wilson and Sons Incorporated repair the valve to proper operating status and submit a copy of the repair receipt within 14 days of the receipt of this letter to:

Andrew Kenney
Cleveland Division of Air Quality
75 Erieview Plaza 2nd Floor
Cleveland, Ohio 44114-1839

Your response to this letter must be received by CDAQ within fourteen (14) days of your receipt of this letter. If there is insufficient time to correct the alleged violations within this timeframe, your response must include a timeline for correcting the alleged violations.



Violations of Ohio air pollution laws and /or permit terms and conditions are subject to the penalties stipulated in Ohio Revised Code Section 3704.99(A), which allows fines of not more than twenty-five thousand dollars or imprisonment for not more than one year, or both, for each violation.

Free assistance with state and/or federal regulations, rules, laws or permit conditions can be provided at no charge through the Ohio EPA Office of Compliance Assistance and Pollution Prevention (OCAPP). OCAPP can be contacted at <http://www.epa.state.oh.us/ocapp> or (614) 644-3469 or (800) 329-7518.

CDAQ makes no guarantee that the facility will meet the qualifying guidelines established by OCAPP.

OCAPP can also provide assistance to facilities that want to investigate methods of pollution prevention to reduce raw material usage and waste production. Again, there is no charge for their services.

CDAQ issues this letter with Ohio EPA's concurrence. The failure to mention any specific violation does not excuse any violations of local, state and federal laws or regulations regarding air pollution control. Violations of air pollution control laws may be pursued in local court or referred to Ohio EPA or U.S. EPA for further enforcement action. Should you have any questions, please call Andrew Kenney at 216-420-7683. All correspondence with CDAQ must include the Ohio EPA facility identification number for Wilson and Sons Incorporated: 1318356236.

Sincerely,

George Baker
Chief of Enforcement

GB/ak

cc: Richard Nemeth and Michael J. Krzywicki, CDAQ
John Paulian, Ohio EPA Central Office
Lisa Holscher, U.S. EPA Region V
Facility File and L:\Data\Facilities\1318356236\2009-7-20 NOV.doc