

CITY OF TOLEDO



DEPARTMENT OF PUBLIC UTILITIES

October 6, 2008

CERTIFIED MAIL

WARNING LETTER

Bill Rupert
BP-Husky Refining LLC.
P.O. Box 696
Toledo, Ohio 43697-0696

Re: TIU Mix Drum CEMS Excessive Downtime

Dear Mr. Rupert:

This letter is in regards to the second quarter of 2008 report submitted on July 18, 2008, for H₂S Continuous Emissions Monitoring Systems (CEMS) which monitors refinery fuel from the TIU Mix Drum serving the following emissions units: B013, B014, B015, B017, B018, B019, B022, B029, B030, B031, B033, and P007. The report indicates that the percent of CEMS downtime was greater than 5 % of the total operating time during the reported quarter.

Please be aware that future quarters of excess emissions/CEMS downtime may result in a Notice of Violation.

If you have any questions, please feel free to contact me at 419-936-3936.

Yours from Toledo - a City of the Future!

A handwritten signature in cursive script that reads "Peter Park".

Peter Park
Engineer

cc: Karen Granata
Leslie A. Kovacik, City of Toledo
John Paulian, Ohio EPA
Lisa Holscher, US EPA