



AKRON REGIONAL
AIR QUALITY MANAGEMENT DISTRICT

Agent of the Ohio Environmental Protection Agency • Division of the Akron Health Department
Serving Medina, Portage and Summit Counties

TELEPHONE: (330) 375-2480
FAX: (330) 375-2402

L. M. Malcolm, P.E.
Administrator

May 12, 2009

Ms. Cecy Kinne
Speedway SuperAmerica, LLC
PO Box 1500
Springfield, OH 45501

Dear Ms. Kinne:

On May 6, 2009, a representative of the Akron Regional Air Quality Management District inspected the Speedway SuperAmerica #3505 gasoline dispensing facility located at 10769 North Street in Garrettsville to determine compliance with OAC 3745-21-09 (DDD) regarding Stage II vapor recovery.

Inspection results/Deficiencies:

Record keeping: No record keeping was available for review. **Speedway Super America #3505 is in violation of OAC rule 3745-21-09 (DDD)(3) which specifies record keeping and its availability.** A certificate of Stage II training must be obtained and a copy placed in the Station file.

Equipment: This facility failed Stage II testing on 5/6/09. Repair and retesting are to be completed within 30 days.

Please correct the deficiencies noted. This facility will be inspected on an annual basis for compliance with the Stage II vapor recovery rule. It is required that you keep record keeping information at a readily available location for inspection. For this Agency, it is requested that you keep copies of the required information at each individual location where all employees can access them.

Thank you for your cooperation and assistance in this matter. If you have any questions, please contact me at 330/375-2480 x6053.

Sincerely,

Susan Anderson
Sanitarian II

SA

CITICENTER - SUITE 904

146 SOUTH HIGH STREET • AKRON, OHIO 44308

An equal opportunity employer and provider of services - CRA 1964



Printed on Recycled Paper