



State of Ohio Environmental Protection Agency

**Southeast District Office**

2195 Front Street  
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

June 15, 2010

**Re:** Washington County  
Asphalt Materials Plants #2 and 3  
Compliance Inspection  
Correspondence (IWW)

Mr. Larry Ruble, Plant Manager  
Asphalt Materials, Inc.  
13925 State Route 7  
Marietta, Ohio 45750

Dear Mr. Ruble:

On May 26, 2010, I conducted inspections at Asphalt Materials, Inc. Plants #2 and 3 (North and South Plants). The purpose of the inspections was to determine Asphalt Materials compliance with its National Pollutant Discharge Elimination System (NPDES) Permit at each facility. I met with you at the South Plant and Mr. Tim Ruble at the North Plant.

As a result of my inspections, I have the following comments:

1. All of the discharge locations and wastewater equipment at the South Plant were observed during the inspection. No problems were noted during the inspection for the South Plant.
2. At the North Plant, one problem was observed during the inspection, the spillage of some asphalt onto the ground below the mixers on the tanks in the north dike area. Mr. Tim Ruble described the operation of the mixers and the reason for the spillage. Mr. Tim Ruble stated the area would be cleaned up. The diked areas are equipped with valves to help prevent the discharge of any of this material.

In conclusion, the Asphalt Materials North and South Plants were in compliance with their NPDES Permits at the time of the inspection.

If you have any questions, feel free to contact me at (740)380-5434.

Sincerely,

Stephen Wells  
District Representative  
Division of Surface Water

SW/dh

Enclosure

**NPDES**  
Compliance Inspection Report

**A. NATIONAL DATA SYSTEM CODING**

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
01N00001*FD	OH0006751	May 26, 2010	C	S	2

**B. FACILITY DATA**

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Asphalt Materials Inc., Marietta Plant 3 (South Plant) 13952 State Route 7 Marietta, Ohio 45750	1:50 p.m.	August 1, 2008
	Exit Time	Permit Expiration Date
	2:20 p.m.	July 31, 2013

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Larry Ruble, Plant Manager	(740) 374-5100
Name, Address and Title of Responsible Official	Phone Number
Larry Ruble, Plant Manager Asphalt Materials, Inc. 13925 State Route 7 Marietta, Ohio 45750	(740) 374-5100

**C. AREAS EVALUATED DURING INSPECTION**

- |                                      |                                       |                                     |
|--------------------------------------|---------------------------------------|-------------------------------------|
| <u>  </u> S Permit                   | <u>  </u> S Flow Measurement          | <u>  </u> N/A Pretreatment          |
| <u>  </u> S Records/Reports          | <u>  </u> N Laboratory                | <u>  </u> N/A Compliance Schedules  |
| <u>  </u> S Operations & Maintenance | <u>  </u> S Effluent/Receiving Waters | <u>  </u> S Self-Monitoring Program |
| <u>  </u> S Facility Site Review     | <u>  </u> N/A Sludge Storage/Disposal | <u>  </u> Other                     |
| <u>  </u> N/A Collection System      |                                       |                                     |


(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

**D. SUMMARY OF FINDINGS/COMMENTS** (attach additional sheets if necessary)

See attached letter.

  
Stephen Wells, Inspector, Ohio EPA, Southeast District Office

6/15/10  
Date

  
Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

6/15/10  
Date