



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korteski, Director

February 11, 2010

Re: Noble County
ODOT Belle Valley Outpost
WWTP Inspection
Correspondence (IWW)

Mr. Larry Woodford, District Deputy Director
Ohio Department of Transportation
District 10
338 Muskingum Drive
Marietta, Ohio 45750

Dear Mr. Woodford:

On January 28, 2010, I conducted a compliance inspection of the ODOT Belle Valley Outpost wastewater treatment facility (WWTP). At the time of my inspection the operation of the plant appeared to be satisfactory.

Recent correspondence was received from the operator, Mr. Soles addressing a recent suspended solids violation in December. At the time of my inspection, the corrective action discussed in the letter to improve filtering was to be the replacement of the pigs and moss in the filtering basin. To prevent future violations you are encouraged to complete the necessary maintenance items in the near future. At the time of my inspection, the discharge was observed clear and free of any oil sheen.

Attached for your review is a detailed compliance inspection report. If there are any questions, please call me at (740) 380-5416.

Sincerely,

Jake Greuey
District Representative
Division of Surface Water

JK/dh

Enclosure

c: Glenn K. Soles, Jr., Operator, Ohio Department of Transportation

**NPDES
Compliance Inspection Report**

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
01N00093*AD	OH0124893	January 28, 2010	C	S	2

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Ohio Dept of Transportation Belle Valley Outpost Township Road 108 Belle Valley, Ohio 43717	3:00 p.m.	June 1, 2006
	Exit Time	Permit Expiration Date
	3:15 p.m.	May 31, 2011

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Glenn K. Soles, Operator	(740) 446-1553
Name, Address and Title of Responsible Official	Phone Number
Larry Woodford, Deputy Director, ODOT District 10 338 Muskingum Drive Marietta, Ohio 45750	

C. AREAS EVALUATED DURING INSPECTION

<u> </u> S Permit	<u> </u> N Flow Measurement	<u> </u> N/A Pretreatment
<u> </u> S Records/Reports	<u> </u> N Laboratory	<u> </u> N/A Compliance Schedules
<u> </u> S Operations & Maintenance	<u> </u> S Effluent/Receiving Waters	<u> </u> S Self-Monitoring Program
<u> </u> S Facility Site Review	<u> </u> N/A Sludge Storage/Disposal	<u> </u> Other
<u> </u> N Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)

The general condition of the oil water separator is satisfactory.

Jake Greuey
Jake Greuey, Inspector, Ohio EPA, Southeast District Office

2/11/10
Date

Timothy M. Campbell
Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

2/11/10
Date