



State of Ohio Environmental Protection Agency

**Southeast District Office**

2195 Front Street  
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

August 5, 2009

**Re: Noble County  
Seneca Lake Baptist  
Compliance Inspection  
Correspondence (PWW)**

Mr. Scott Seder  
Seneca Lake Baptist Assembly  
55819 Skyline Drive  
Senecaville, Ohio 43870

Dear Mr. Seder:

On July 14, 2009, I conducted a Compliance Evaluation Inspection (CEI) of the Seneca Lake Baptist Assembly's wastewater treatment facility. The purpose of the inspection was to determine the facility's compliance status with the terms and conditions of NPDES Permit Number 0GV00009\*AG.

As a result of my inspection, the following observations were made.

1. Observation of the aeration basins and clarifiers showed all treatment units to be fully operational and well maintained.
2. The filter beds were all found to be in good condition with no solids accumulation and all sand raked level and clean.

At the time of my inspection all components of the wastewater treatment plant were in operable condition and the effluent observed clear with no objectionable odors. Enclosed is a copy of my detailed inspection report.

If you have any questions please call me at (740) 380-5416.

Sincerely,

Jake Greuey  
District Representative  
Division of Surface Water

JJG/dh

Enclosure

c: David Mitchell, Operator

**NPDES**  
Compliance Inspection Report

**A. NATIONAL DATA SYSTEM CODING**

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
0GV00009*AG	OHS00002	July 14, 2009	C	S	1

**B. FACILITY DATA**

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Seneca Lake Baptist Assembly 55819 Skyline Drive Senecaville, Ohio 43870	9:45 a.m.	June 5, 2006
	Exit Time	Permit Expiration Date
	10:25 a.m.	December 31, 2009

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Scott Seder, Manager	
Name, Address and Title of Responsible Official	Phone Number
Mr. Scott Seder Seneca Lake Baptist Assembly 55819 Skyline Drive Senecaville, Ohio 43870	

**C. AREAS EVALUATED DURING INSPECTION**

<u>  </u> S Permit	<u>  </u> S Flow Measurement	<u>  </u> N/A Pretreatment
<u>  </u> S Records/Reports	<u>  </u> * Laboratory	<u>  </u> N/A Compliance Schedules
<u>  </u> S Operations & Maintenance	<u>  </u> S Effluent/Receiving Waters	<u>  </u> S Self-Monitoring Program
<u>  </u> S Facility Site Review	<u>  </u> S Sludge Storage/Disposal	<u>  </u> Other
<u>  </u> S Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

**D. SUMMARY OF FINDINGS/COMMENTS** (attach additional sheets if necessary)

\*Contract laboratory used and not evaluated.  
See attached letter.

*Jake Greuey*  
Jake Greuey, Inspector, Ohio EPA, Southeast District Office

8/5/09  
Date

*Timothy M. Campbell*  
Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

8/6/09  
Date