



**Environmental
Protection Agency**

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 15, 2011

Re: Morgan County
Riverside Country Care
CEI -2011
Correspondence (PWW)

Mr. Chris Inverso
Provider Services
16230 Kaylor Drive
Danville, Ohio 43014

Dear Mr. Inverso:

I conducted a Compliance Evaluation Inspection for the Riverside Country Care Center Wastewater Plant. I reviewed the records for the facility on June 3, 2011 with Mr. Mike Wisecarver and visited the site on June 10, 2011. The purpose of the inspection was to determine the compliance of Riverside Country Care Center with NPDES permit number OGS00063*AD and the Ohio Water Pollution Control Act, Revised Code Chapter 6111.

After reviewing our files and conducting a site inspection of the treatment system, I found no apparent violations.

Attached is a copy of the inspection report which indicates the areas evaluated during the inspection. Riverside Country Care Center should take the appropriate actions to maintain the facility in compliance with all terms and conditions of the NPDES permit.

The Ohio EPA strongly encourages pollution prevention as the preferred approach for waste management. The first priority of pollution prevention is to eliminate the generation of wastes and pollutants at the source (source reduction). For those wastes or pollutants that are generated, the second priority is to recycle or reuse them in an environmentally sound manner. You can benefit economically, help preserve the environment, and improve your public image by implementing pollution prevention

programs. For more information about pollution prevention, including fact sheets and U.S. EPA's Facility Pollution Prevention Guide, (EPA/600/R-92/088), you may contact the Ohio EPA Pollution Prevention Section at (614) 644-3469 or me for additional information.

Sincerely,



Scott Foster
Environmental Specialist 2
Division of Surface Water

SF/dh

Enclosure

c: Mike Wisecarver, Operator

**NPDES
Compliance Inspection Report**

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
0GS00063*AD	OHS000003	June 10, 2011	C	S	1

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Riverside Country Care Center 856 South Riverside Drive McConnelsville, Ohio 43756	10:55 am	January 1, 2010
	Exit Time	Permit Expiration Date
	11:05 am	December 31, 2014

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Wisecarver Environmental, Mike Wisecarver; Operator	740-453-1716
Name, Address and Title of Responsible Official	Phone Number
Mr. Chris Inverso Provider Services 16230 Kaylor Drive Danville, Ohio 43014	440-477-9901


C. AREAS EVALUATED DURING INSPECTION

<u>S</u> Permit	<u>S</u> Flow Measurement	<u>N/A</u> Pretreatment
<u>S</u> Records/Reports	<u>S</u> Laboratory	<u>N/A</u> Compliance Schedules
<u>S</u> Operations & Maintenance	<u>S</u> Effluent/Receiving Waters	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>S</u> Sludge Storage/Disposal	<u>N</u> Other
<u>N</u> Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)


See Attached Letter.



Scott Foster, Inspector, Ohio EPA, Southeast District Office

7/15/11

Date



Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

7/15/11

Date