



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

July 14, 2010

Re: Belmont County
Bellaire Corp Mine #5
NPDES Permit #0IL00043*ED
Compliance Evaluation Inspection
Correspondence (IWW)

Mr. Steve Hill, Property Manager
Bellaire Corp.
361 State Route 7 North
Powhatan Point, Ohio 43952

Dear Mr. Hill:

On July 8, 2010, Eric Nygaard, from the Division of Surface Water's permit section in Central Office, and I conducted a Compliance Evaluation Inspection (CEI) of Bellaire Corporation's Powhatan Mine #5 at Town Run. You represented Bellaire Corp. during the inspection. Your engineer, Bill Siplivy, accompanied us on the inspection.

The purpose of the inspection was to assess your compliance status with the terms and conditions of the NPDES permit, federal number OH0011576, state number 0IL00043*ED. Wastewater samples were not collected on this day because the pond was not discharging. A copy of the inspection report form is attached. Based on the inspection, a review of the Discharge Monitoring Report (DMR) data and the permit, the facility appeared to be in compliance on the day of the inspection.

If you have any questions, please contact me at (740) 380-5284 at your convenience.

Sincerely,

Ms. Abbot Stevenson
Environmental Engineer
Permits and Enforcement Section
Division of Surface Water

AS/dh

Enclosure

NPDES Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
0IL00043*ED	OH0011576	7/8/2010	C	S	2

B. FACILITY DATA

Name & Location of Facility Inspected	Entry Time	Permit Effective Date
Bellaire Corp. Mine #5 Town Run State Route 148 and York Township Rd 810 Powhatan Point, OH	10:30 am	8/1/2009
	Exit Time	Permit Expiration Date
	1:00 pm	7/31/2014


Name(s) & Title(s) of On-Site Representative(s)	Phone Number(s)
Steven Hill, Property Manager Bill Siplivy, PE	740/495-4346
Name, Address, & Title of Responsible Official	Phone Number
Steven Hill Bellaire Corp. 361 Highway 7 North Powhatan Point, OH 43942	740/495-4346

C. AREAS EVALUATED DURING INSPECTION

<u>S</u> Permit	<u>S</u> Flow Measurement	<u>N/A</u> Pretreatment
<u>S</u> Records/Reports	<u>S</u> Laboratory	<u>N/A</u> Compliance Schedules
<u>S</u> Operations & Maintenance	<u>S</u> Effluent/Receiving Waters	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>S</u> Sludge Storage/Disposal	<u> </u> Other
<u>N/A</u> Collection System		

(S = Satisfactory; M = Marginal; U = Unsatisfactory; N = Not Evaluated; N/A = Not Applicable)


D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)



 Abbot Stevenson, Inspector, Ohio EPA, Southeast District Office

7/15/10

 Date



 Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

7/15/10

 Date