



State of Ohio Environmental Protection Agency

**Southeast District Office**

2195 Front Street  
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

July 17, 2008

**Re: Belmont County  
Tri-State Asphalt Flyash Landfill  
Reconnaissance Inspection  
Correspondence (IWW)**

Mr. Glenn Straub  
Tri-State Group, Inc.  
Tri-State Asphalt Corporation  
56290 Dilles Bottom Road  
Shadyside, Ohio 43947

Dear Mr. Straub:

On May 29, 2008, Ken Mettler and I conducted a reconnaissance inspection at the Tri-State Asphalt Flyash Landfill facility. The purpose of the inspection was to see if construction on the landfill final closure had begun. There was construction activity on the site the day of the inspection. A copy of the inspection report form is attached.

If you have any questions, please contact me at your convenience at (740) 380-5284 or by e-mail at [abbot.stevenson@epa.state.oh.us](mailto:abbot.stevenson@epa.state.oh.us).

Sincerely,

Abbot Stevenson  
Environmental Engineer  
Division of Surface Water

AS/dh

- c: Timothy Kern, AGO
- c: Jane Jacobs, DDAGW
- c: Mike Kearns, Hamilton and Associates, Inc.
- c: Larry Zink, Zink, Zink and Zink

**NPDES  
Compliance Inspection Report**

**A. NATIONAL DATA SYSTEM CODING**

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
0IN00107*AD	OH0076813	5/29/08	R	S	2

**B. FACILITY DATA**

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Tri State Asphalt Flyash Landfill 56290 Dilles Bottom Rd. Shadyside, OH 43947	10:30 am	12/12/1985
	Exit Time	Permit Expiration Date
	10:45 am	12/9/1990

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
NA	
Name, Address and Title of Responsible Official	Phone Number
Glenn Straub, President Tri State Group Inc. 7745 Wood Duck Rd., Boca Raton, FL 33434	561/798-7333


**C. AREAS EVALUATED DURING INSPECTION**

<u>U</u> Permit	<u>N</u> Flow Measurement	<u>NA</u> Pretreatment
<u>N</u> Records/Reports	<u>N</u> Laboratory	<u>U</u> Compliance Schedules
<u>S</u> Operations & Maintenance	<u>NA</u> Effluent/Receiving Waters	<u>N</u> Self-Monitoring Program
<u>N</u> Facility Site Review	<u>NA</u> Sludge Storage/Disposal	<u>    </u> Other
<u>NA</u> Collection System		


(S = Satisfactory; M = Marginal; U = Unsatisfactory; N = Not Evaluated)

**D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)**

1. Permit – the permit does not reflect current conditions at the site.
2. Operations and Maintenance – Additional closure work has begun on site. A dump truck was dumping loads of soil on the flyash site.
3. Compliance Schedule – permittee is in non-compliance with the schedules contained in the 2003 Judgment, however, the facility is in compliance with the deadlines contained in the 2/4/08 Judgment.

  
Abbot Stevenson, Inspector, Ohio EPA, Southeast District Office

7/17/08  
Date

  
Timothy Campbell, Reviewer, Ohio EPA, Southeast District Office

7/17/08  
Date