



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

March 19, 2010

Re: Guernsey County
Cochran's Market
WWTP Inspection
Correspondence (PWW)

Mr. Jim Hershberger
18787 Cadiz Road
Lore City, Ohio 43755

Dear Mr. Hershberger:

On March 15, 2010, I conducted a compliance evaluation inspection (CEI) of the Cochran's Market wastewater treatment plant. The purpose of the inspection was to determine compliance with the terms and conditions of National Pollutant Discharge Elimination System (NPDES) permit number OGV00014*BG.

At the time of my inspection the treatment plant was found to be in good condition with all necessary treatment units in operation. Prior to May 1st, the chlorinator should be repaired to allow for disinfection which is required from May 1st through October 31st. During my inspection, there was little flow and no discharge was observed although the treated effluent in the chlorine contact tank was relatively clear with no odor.

Attached is a copy of my detailed inspection report for your review. If you have any questions, please contact me at (740) 380-5416.

Sincerely,

Jake Greuey
District Site Representative
Division of Surface Water

JJG/dh

Enclosure

c: Shane Cochran, Operator of Cochran's Market
c: Matt Stiers, WWTP Operator

**NPDES
Compliance Inspection Report**

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
OGV00014*BG	OHS000003	March 15, 2010	C	S	1

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Cochran's Market WWTP 228 Old National Road Old Washington, Ohio	12:05 p.m.	November 1, 2006
	Exit Time	Permit Expiration Date
	12:20 p.m.	October 31, 2011

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Shane Cochran, Business Owner	
Name, Address and Title of Responsible Official	Phone Number
James Hershberger, Owner 18787 Cadiz Road Lore City, Ohio 43755	

C. AREAS EVALUATED DURING INSPECTION

<u> </u> S Permit	<u> </u> S Flow Measurement	<u> </u> N/A Pretreatment
<u> </u> S Records/Reports	<u> </u> * Laboratory	<u> </u> N/A Compliance Schedules
<u> </u> S Operations & Maintenance	<u> </u> S Effluent/Receiving Waters	<u> </u> S Self-Monitoring Program
<u> </u> S Facility Site Review	<u> </u> N/A Sludge Storage/Disposal	<u> </u> Other
<u> </u> N/A Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)

See attached letter.

* Laboratory analysis is conducted by a contract lab which was not evaluated.



 Jake Greuey, Inspector, Ohio EPA, Southeast District Office

3/19/10

 Date



 Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

3/19/10

 Date