



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

March 24, 2009

Re: Guernsey County
Couto's Pizza and Subs
Reconnaissance Inspection
NPDES Permit #0PR00099*CD
Correspondence (PWV)

Mr. Larry Couto
P.O. Box 313
Buffalo, Ohio 43722

Dear Mr. Couto:

On March 11, 2009, I conducted a reconnaissance inspection of the Couto's Pizza and Subs wastewater treatment plant. The purpose of the inspection was to determine compliance with the terms and conditions of National Pollutant Discharge Elimination System (NPDES) permit number 0PR00099*CD. Matt Stiers, plant operator was present during my inspection.

At the time of my inspection, all components of the treatment system were fully operational. The filter beds were found to be in good condition as flow was recently switched to a new bed and the other bed was in the process of being cleaned. The remaining solids should be removed from the dirty filter bed and the sand raked level in preparation for future use.

At the time of my inspection, the effluent was clear with very little suspended solids and no objectionable odor. Attached is a copy of my detailed inspection report. If you have any questions, please contact me at (740) 380-5416.

Sincerely,

Jake Greuey
District Representative
Division of Surface Water

JGG/dh

Enclosure

c: Matt Stiers, Operator

NPDES
Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
0PR00099*CD	OH0104051	March 11, 2009	R	S	1

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Couto's Pizza and Subs 56500 Vocational Road Buffalo, Ohio	9:00 a.m.	August 1, 2006
	Exit Time	Permit Expiration Date
	9:20 a.m.	July 31, 2011

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Matt Stiers, Operator	
Name, Address and Title of Responsible Official	Phone Number
Mr. Larry Couto P.O. Box 313 Buffalo, Ohio 43722	

C. AREAS EVALUATED DURING INSPECTION

<input checked="" type="checkbox"/> Permit	<input checked="" type="checkbox"/> Flow Measurement	<input type="checkbox"/> Pretreatment
<input checked="" type="checkbox"/> Records/Reports	<input type="checkbox"/> * Laboratory	<input checked="" type="checkbox"/> Compliance Schedules
<input checked="" type="checkbox"/> Operations & Maintenance	<input checked="" type="checkbox"/> Effluent/Receiving Waters	<input checked="" type="checkbox"/> Self-Monitoring Program
<input checked="" type="checkbox"/> Facility Site Review	<input type="checkbox"/> Sludge Storage/Disposal	<input type="checkbox"/> Other
<input type="checkbox"/> Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)

See attached letter.


* Laboratory analysis is conducted by a contract lab which was not evaluated.



Jake Greuey, Inspector, Ohio EPA, Southeast District Office

3/23/09

Date



Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

3/23/09

Date