



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

February 17, 2010

Re: Muskingum County
Maysville Regional Water WTP
2010 CEI
CORRESPONDENCE (IWW)

Beth Lyon, General Manager
Maysville Regional Water
6255 Maysville Pike
Zanesville, Ohio 43702

Dear Ms. Lyon:

On January 28, 2010, I conducted a Compliance Evaluation Inspection at Maysville Regional Water WTP located in Zanesville, Ohio. Aaron Wolfe, with this office, assisted me with the inspection. You represented Maysville Regional Water and accompanied me during the inspection. The purpose of the inspection was to determine Maysville Regional's compliance with NPDES Permit Number 0IV00061*BD and the Ohio Water Pollution Control Act, Revised Code Chapter 6111.

As a result of the inspection and review of our files, I found no apparent violations.

The Ohio EPA strongly encourages pollution prevention as the preferred approach for waste management. The first priority of pollution prevention is to eliminate the generation of wastes and pollutants at the source (source reduction). For those wastes or pollutants that are generated, the second priority is to recycle or reuse them in an environmentally sound manner. You can benefit economically, help preserve the environment, and improve your public image by implementing pollution prevention programs. For more information about pollution prevention, including fact sheets and U.S. EPA's Facility Pollution Prevention Guide, (EPA/600/R-92/088), you may contact the Ohio EPA Pollution Prevention Section at (614) 644-3469 or me for additional information.

Sincerely,

Scott Foster
Environmental Specialist 2
Division of Surface Water

SF/mlm

NPDES
Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
0IV00061*BD	OH0120669	January 28, 2010	C	S	2

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Maysville Regional Water WTP 6255 Maysville Pike Zanesville, Ohio 43702	3:00 PM	August 1, 2009
	Exit Time	Permit Expiration Date
	3:30 PM	July 31, 2014

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Beth Lyon, General Manager	740-849-2428
Name, Address and Title of Responsible Official	Phone Number
Beth Lyon, General Manager 6255 Maysville Pike Zanesville, Ohio 43702	740-849-2428


C. AREAS EVALUATED DURING INSPECTION

<u>S</u> Permit	<u>N/A</u> Flow Measurement	<u>N/A</u> Pretreatment
<u>S</u> Records/Reports	<u>N/A</u> Laboratory	<u>N/A</u> Compliance Schedules
<u>S</u> Operations & Maintenance	<u>S</u> Effluent/Receiving Waters	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>N/A</u> Sludge Storage/Disposal	<u>N/A</u> Other
<u>N/A</u> Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)


See Attached Letter. This facility operates without a discharge and has not removed solids or discharged in the past 2 years.



Scott Foster, Inspector, Ohio EPA, Southeast District Office

2/18/10

Date



Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

2/18/10

Date