



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

August 5, 2009

Re: Muskingum County
Riverview Manor MHP and Apt.
CEI- 2009
Correspondence (PWW)

Mr. Keith Shrider, Owner
Riverview Manor MHP & Apt.
P.O. Box 2041
Zanesville, Ohio 43702

Dear Mr. Shrider:

On June 4, 2009, I conducted a Compliance Evaluation Inspection for the Riverview Manor MHP and Apartment Wastewater Facility. I was accompanied by Pete Foster, Maintenance Operator, and you. The purpose of the inspection was to determine your compliance with your NPDES permit and to follow up on a complaint received from the Muskingum County Health Department. The following are comments from the inspection:


The lids on the tanks to the treatment plant appeared to be in good condition and I have attached a photo of the lids. I had received a complaint on May 29, 2009 from the Muskingum County Health Department that during their inspection of your facility, the lids on the tanks appeared to be broken.

You informed me that you had Zemba's pump out the trash tank and upon inspection, it appeared to have been pumped. You showed me a ticket from Zemba Brothers as proof that the tank was pumped after the health department's inspection. This was also an issue from the complaint of May 29, 2009 from the local health department.

We discussed your work in the collection system and the improvements that have been made. I marked the collection system as marginal because of increased flows in the treatment facility during storm events. This is a good indication of I/I and a program to abate the I/I should be implemented. Inform the Ohio EPA of future plans for collection system repairs. We also discussed the future cleaning of a drainage ditch.

If you have any questions or comments, please feel free to call me at (740) 380-5227. Please respond to this letter by August 28, 2009. Attached is a copy of the inspection report.

Sincerely,



Scott Foster
Environmental Specialist 2
Division of Surface Water

SF/dh

Enclosure

- c: Mike Wisecarver, Operator
- c: Mike Kirsch, Muskingum County Health Department

NPDES Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
0PV00029*BD	OH0127647	June 4, 2009	C	S	1

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Riverview Manor MHP & Apt 1710 South River Road Zanesville, Ohio 43701	10:40 am	August 1, 2006
	Exit Time	Permit Expiration Date
	11:10 am	July 31, 2011

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Mike Wisecarver, Operator	740-453-1716
Name, Address and Title of Responsible Official	Phone Number
Keith Shrider, Owner PO Box 2041 Zanesville, Ohio 43702	740-453-5552


C. AREAS EVALUATED DURING INSPECTION

<u>S</u> Permit	<u>S</u> Flow Measurement	<u>N/A</u> Pretreatment
<u>S</u> Records/Reports	<u>S</u> Laboratory	<u>N/A</u> Compliance Schedules
<u>S</u> Operations & Maintenance	<u>S</u> Effluent/Receiving Waters	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>S</u> Sludge Storage/Disposal	<u>N</u> Other
<u>M</u> Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)

See Attached Letter.



 Scott Foster, Inspector, Ohio EPA, Southeast District Office

8/4/09

 Date



 Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

8/4/09

 Date

