



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

September 15, 2010

Re: Morgan County
Malta Collection System
2011 CEI
Correspondence (PWW)

Mr. Darrin Carpenter, Village Administrator
Village of Malta
PO Box 307
Malta, Ohio 43758

Dear Mr. Carpenter:

On August 20, 2010 I conducted a Compliance Evaluation Inspection at Malta's Collection System located in Malta, Ohio. You represented Malta and accompanied me during the inspection. The purpose of the inspection was to determine Malta's compliance with NPDES Permit Number OPA00095*DD and the Ohio Water Pollution Control Act, Revised Code Chapter 6111.

As a result of the inspection and review of our files, I have the following comments:

The sewer separation project is to be out for bid in September of 2010 and construction will commence in early 2011. You also informed me that an inline flow meter will be installed on the sewer line going to McConnelsville during Phase 1. The line will also be inspected by camera and repaired, if needed.

Attached is a copy of the inspection report. Malta should take the appropriate actions to maintain the facility to compliance with all terms and conditions of the NPDES permit.

The Ohio EPA strongly encourages pollution prevention as the preferred approach for waste management. The first priority of pollution prevention is to eliminate the generation of wastes and pollutants at the source (source reduction). For those wastes or pollutants that are generated, the second priority is to recycle or reuse them in an environmentally sound manner. You can benefit economically, help preserve the environment, and improve your public image by implementing pollution prevention programs. For more information about pollution prevention, including fact sheets and U.S. EPA's Facility Pollution Prevention Guide, (EPA/600/R-92/088), you may contact the Ohio EPA Pollution Prevention Section at (614) 644-3469 or me for additional information.

Sincerely,

Scott Foster
District Representative
Division of Surface Water

SF/mlm

NPDES
Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
OPA00095*DD	OH0094528	August 20, 2010	C	S	1

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Village of Malta Malta Collection System P.O. Box 307 Malta, Ohio 43758	12:15 p.m.	May 1, 2008
	Exit Time	Permit Expiration Date
	12:40 p.m.	April 30, 2013

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Darrin Carpenter, Village Administrator	(740) 962-4971
Name, Address and Title of Responsible Official	Phone Number
Darrin Carpenter, Village Administrator P.O. Box 307 Malta, Ohio 43758	(740) 962-4971


C. AREAS EVALUATED DURING INSPECTION

<u>S</u> Permit	<u>S</u> Flow Measurement	<u>N/A</u> Pretreatment
<u>S</u> Records/Reports	<u>N/A</u> Laboratory	<u>S</u> Compliance Schedules
<u>S</u> Operations & Maintenance	<u>S</u> Effluent/Receiving Waters	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>N/A</u> Sludge Storage/Disposal	<u>N</u> Other
<u>S</u> Collection System		

(S = Satisfactory; M = Marginal; U = Unsatisfactory; N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)


See attached letter.



Scott Foster, Inspector, Ohio EPA, Southeast District Office

9/15/10

Date



Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

9/15/10

Date