



**Environmental
Protection Agency**

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

April 26, 2011

Re: Morgan County
Miba Sinter US LLC
2011 CEI
Correspondence (IWW)

Ms. Heidi Suhoski, Env. Health and Safety Coord.
Miba Sinter US LLC
5045 North State Route 60
McConnelsville, Ohio 43756

Dear Ms. Suhoski:

On April 6, 2011, I conducted a Compliance Evaluation Inspection at Miba Sinter US LLC located in McConnelsville, Ohio. You represented Miba Sinter and accompanied me during the inspection. The purpose of the inspection was to determine Miba Sinter's compliance with NPDES Permit Number 0IS00025*AD and the Ohio Water Pollution Control Act, Revised Code Chapter 6111.

As a result of the inspection and review of our files, I found no apparent violations.

Attached is a copy of the inspection report which indicates all areas that were evaluated as satisfactory. Miba Sinter should take the appropriate actions to maintain the facility in compliance with all terms and conditions of the NPDES permit.

The Ohio EPA strongly encourages pollution prevention as the preferred approach for waste management. The first priority of pollution prevention is to eliminate the generation of wastes and pollutants at the source (source reduction). For those wastes or pollutants that are generated, the second priority is to recycle or reuse them in an environmentally sound manner. You can benefit economically, help preserve the environment, and improve your public image by implementing pollution prevention programs. For more information about pollution prevention, including fact sheets and U.S. EPA's Facility Pollution Prevention Guide, (EPA/600/R-92/088), you may contact the Ohio EPA Pollution Prevention Section at (614) 644-3469 or me for additional information.

Sincerely,

Scott Foster
Environmental Specialist 2
Division of Surface Water

SF/dh

Enclosure

c: Steve Crise, Plant Manager

NPDES
Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
0IS00025*AD	OH0139807	April 6, 2011	C	S	2

B. FACILITY DATA

Name & Location of Facility Inspected	Entry Time	Permit Effective Date
Miba Sinter US LLC 5045 North State Route 60 McConnelsville, Ohio 43756	9:21 a.m.	July 1, 2009
	Exit Time	Permit Expiration Date
	11:45 a.m.	June 30, 2014

Name(s) & Title(s) of On-Site Representative(s)	Phone Number(s)
Heidi Suhoski, Environmental Health and Safety Coordinator	(740) 962-4242 Ext. 100
Name, Address, & Title of Responsible Official	Phone Number
Steve Crise, Plant Manager Miba Sinter US LLC 5045 State Route 60 McConnelsville, Ohio 43756	(740) 962-4242 Ext. 1508


C. AREAS EVALUATED DURING INSPECTION

<u>S</u> Permit	<u>S</u> Flow Measurement	<u>N/A</u> Pretreatment
<u>S</u> Records/Reports	<u>S</u> Laboratory	<u>N/A</u> Compliance Schedules
<u>S</u> Operations & Maintenance	<u>S</u> Effluent/Receiving Waters	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>N/A</u> Sludge Storage/Disposal	<u>N</u> Other
<u>N/A</u> Collection System		

(S = Satisfactory; M = Marginal; U = Unsatisfactory; N = Not Evaluated; N/A = Not Applicable)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)


See Attached Letter.



Scott Foster, Inspector, Ohio EPA, Southeast District Office

4/26/11

Date



Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

4/26/11

Date