



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

December 28, 2009

RE: RES SITE B LANDFILL  
GROUND WATER MONITORING  
NOTICE OF VIOLATION

**CERTIFIED MAIL**

Yogi Chokski  
Reserve Environmental Services  
4633 Middle Road  
P.O. Box 1038  
Ashtabula, Ohio 44004

Dear Mr. Chokshi:

The Ohio Environmental Protection Agency (Ohio EPA) has reviewed the document titled "Site B Industrial Solid Waste Disposal Facility, Semiannual Groundwater Monitoring Results 1<sup>st</sup> Semiannual Event 2008." It was dated 2008 and it was received by Ohio EPA on November 19, 2008. The report was submitted by Reserve Environmental Services (RES) in regards to the Site B landfill. The owner/operator of RES is responsible for conducting ground water monitoring in accordance with Ohio Administrative Code (OAC) Rules 3745-29-10 and 3745-30-08, as effective August 15, 2003.

Analytical results indicate that there has been no statistically significant increase in chloride, ammonia or COD. However, required statistical analyses of other Appendix III-H parameters were not performed. The document was not submitted within 75 days of sampling, and some of the documentation is missing. RES is, therefore, in violation of the following:

1. **OAC 3745-30-08(D)(4)** states "After the initial year, all monitoring wells shall be sampled at least semi-annually and the samples analyzed for the indicator parameters specified either in appendix III of this rule for the owner or operator's waste(s) or in the alternate parameter list approved in accordance with paragraph (D)(2) of this rule. The owner or operator shall statistically analyze the results for these required indicator parameters in accordance with paragraph (C)(7) of this rule. The number and kinds of samples collected shall be consistent with the statistical method used to analyze the data and shall be as often as necessary to ensure, with reasonable confidence, that a contaminant release to the ground water from the facility will be detected."

**OAC 3745-30-08(D)(6)** states "Ground water samples shall be field analyzed for temperature, specific conductance, and pH whenever a sample is withdrawn from a monitoring well."

The owner/operator failed to obtain at least two semiannual groundwater samples during 2008 and failed to monitor for temperature, specific conductance and pH each time the well is sampled. According to Appendix III-H parameter list, the following double starred parameters are required to be monitored at least twice per year and the single starred parameters are required to be monitored each time the well is sampled:

*Temperature\**  
*Specific conductance\**  
*pH\**  
*Ammonia\*\**  
*Calcium\*\**  
*Chloride\*\**  
*Iron\*\**  
*Nitrate-nitrite\*\**  
*Potassium\*\**  
*Sodium\*\**  
*Sulfate\*\**  
*Total alkalinity\*\**

Upon review of the document, it was determined that the analytical data provided in the document was the annual monitoring (Appendix III-H parameters) data that was conducted on July 10-11, 2008. Therefore, the document was actually the second semiannual ground water monitoring event. The first semiannual ground water monitoring event was not completed. Similarly, only annual monitoring was conducted in 2004 and 2005, and 2007, so this is a serious and persistent issue.

2. **OAC 3745-30-08(D)(4)** states *"After the initial year, all monitoring wells shall be sampled at least semi-annually and the samples analyzed for the indicator parameters specified either in appendix III of this rule for the owner or operator's waste(s) or in the alternate parameter list approved in accordance with paragraph (D)(2) of this rule. The owner or operator shall statistically analyze the results for these required indicator parameters in accordance with paragraph (C)(7) of this rule. The number and kinds of samples collected shall be consistent with the statistical method used to analyze the data and shall be as often as necessary to ensure, with reasonable confidence, that a contaminant release to the ground water from the facility will be detected."*

The owner/operator failed to conduct statistical analyses on the Appendix III-H semiannual parameters in order to determine if any of the downgradient wells have exceeded background concentrations for any of these parameters. The owner/operator only performed statistical analyses on chloride, ammonia and COD. However, statistical analysis was not completed for the remaining parameters and the director of Ohio EPA has not approved an alternate parameters list.

To achieve compliance with this rule, statistical analyses must be performed on all the Appendix III-H parameters for which there are detections.

3. **OAC 3745-30-08(D)(4)** states *"All ground water analysis results, statistical analysis results, and ground-water elevation data generated in accordance with paragraphs (C), (D), (E), and (F) of this rule shall be submitted to Ohio EPA not later than seventy-five days after sampling the well. All ground water data and accompanying text shall be submitted on a form specified by the director."*

The owner/operator failed to submit all ground water analysis results, statistical analysis results, and groundwater elevation data to Ohio EPA within seventy-five days after sampling the well(s). The wells were sampled on July 10-11, 2008 but the ground water analysis results, statistical analysis results, and ground-water elevation data was not received by Ohio EPA until November 19, 2008 (131 days after sampling).

To avoid future violations this data and analyses must be submitted to Ohio EPA not later than seventy-five days after sampling the wells.

**OAC 3745-30-08(C)(1)(b)** states, in part, that the ground water monitoring program shall include consistent sampling and analysis procedures that are designed to ensure monitoring results that provide an accurate representation of ground water quality at the background and downgradient wells and shall include a detailed description of the equipment, procedures, and techniques to be used for the collection of ground water samples *"Collection of ground water samples, including (i) Well evacuation. (ii) Sample withdrawal. (iii) Sample containers and handling. (iv) Sample preservation."*

The owner/operator failed to provide sufficient uncompromised VOC sample analysis. Ohio EPA noted that the laboratory Sample Receiving Summary Log reported head space in VOC samples for monitoring wells 804R, 811D, 932S and 808D. The lab analyses for VOCs were included in the laboratory report for these wells without qualification.

The owner/operator must assure that VOC samples are collected and submitted for lab analysis without headspace. In the event that a sample is compromised the laboratory report should be qualified and the VOC data for these wells removed from the data set. Upon notification from the laboratory of a compromised sample, the owner/operator would be expected to immediately resample to obtain an uncompromised sample for analysis.

4. **OAC 3745-30-08(C)(1)(c)** states that the ground water monitoring program shall include consistent sampling and analysis procedures ... that are designed to ensure

monitoring results that provide an accurate representation of ground water quality at the background and downgradient wells ... shall, at a minimum, include a detailed description of the equipment, procedures, and techniques to be used for the *“Performance of field analysis, including the following: (i) Procedures and forms for recording raw data and the exact location, time, and facility-specific conditions associated with the data acquisition [and] (ii) Calibration of field devices.”*

The owner/operator failed to submit field notes including field analyses and equipment calibration records for all wells sampled. The field forms are important to determine whether field methods employed during measurement, purging and sampling resulted in the collection of samples that were representative of ground water quality at the sampling locations and that field QA/QC procedures were employed.

Field notes obtained during measurement, purging, field analysis and sampling of the wells must be submitted to comply with this rule.

5. **OAC 3745-30-08(C)(2)** states that *“Ground water elevations shall be measured within a single twenty-four-hour period in all monitoring wells at least semi-annually and in each well prior to purging and sampling. The owner or operator shall determine, for the uppermost aquifer system and for all significant zones of saturation monitored, the direction of ground-water flow at least semi-annually. The ground water elevations and direction(s) of flow shall be shown on a potentiometric map(s) submitted with the sampling data.”*

The owner/operator failed to show water level elevations for each well on the potentiometric maps and failed to obtain water level elevations semiannually during 2008.

The owner/operator must submit revised potentiometric surface maps that show legibly the water level elevations for each well (and the well numbers). (It is suggested that in addition to the whole facility map, the owner/operator may wish to prepare potentiometric maps solely for Site B in order to minimize the size of the map needed). In the future water level elevations must be measured and potentiometric maps prepared twice per year.

In addition, to the above violations, Ohio EPA has the following comments:

1. The owner/operator has provided insufficient information to determine compliance with OAC Rule 3745-30-08(C)(2) which requires that water level measurements be obtained within 24 hours.

Yogi Chokski  
Reserve Environmental Services  
December 28, 2009  
Page 5

The owner/operator must provide the date(s) on which the site B water level data was obtained.

Please respond to this letter in writing within fourteen (14) days to indicate how you have abated or will abate the above violations.

Nothing in this letter shall be construed to authorize any waiver from the requirements of any applicable state or federal laws or regulations. This letter shall not be interpreted to release the owner/operator of RES from responsibility under Chapters 3704, 3714, 3734, or 6111 of the Ohio Revised Code or under the Federal Clean Water or Comprehensive Environmental Response, Compensation, and Liability Acts for remedying conditions resulting from any release of contaminants to the environment.

If you have any technical questions regarding this review, please contact Kathryn Epp at (330) 963-1233. Please submit all correspondence to Colum McKenna, Division of Solid and Infectious Waste Management, Northeast District Office, Ohio EPA, 2110 East Aurora Road, Twinsburg, Ohio 44087.

Sincerely,



Colum McKenna  
Environmental Specialist  
Division of Solid and Infectious Waste Management

CJM:cl

cc: Kathryn Epp, NEDO-DDAGW  
Ray Saporito, Ashtabula County Board of Health  
File: [Kurko/LAND/RES Site B Landfill/GRO/04]

*2/3/12 2099*

**U.S. Postal Service**  
**CERTIFIED MAIL RECEIPT**

(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at [www.usps.com](http://www.usps.com)

7009 1680 0000 6381 2876

Postage	\$
Certified Fee	
Return Receipt Fee (Endorsement Required)	
Restricted Delivery Fee (Endorsement Required)	
Total Postage & Fees	\$

2008 GW  
 Researched  
 Env. +  
 Postmark  
 Here (11)  
 12-29-09

Sent To Yogi Chokski  
 Street, Apt. No.,  
 or PO Box No. Reserve Env. Services  
 City, State, ZIP+4

PS Form 3800, August 2006 See Reverse for Instructions

**SENDER: COMPLETE THIS SECTION**

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:  
 Yogi Chokski  
 Reserve Environmental Services  
 4633 Middle Road  
 P.O. Box 1038  
 Ashtabula, Ohio 44004

**COMPLETE THIS SECTION ON DELIVERY**

A. Signature  Agent  
 Addressee

B. Received by (Printed Name) DONALD K. KOSKI C. Date of Delivery 12-31-09

D. Is delivery address different from item 1?  Yes  
 No  
 If YES, enter delivery address below:

3. Service Type  
 Certified Mail  Express Mail  
 Registered  Return Receipt for Merchandise  
 Insured Mail  C.O.D.

4. Restricted Delivery? (Extra Fee)  Yes

2. Article Number (Transfer from service label) 7609 1680 0000 6381 2876 C. hr. Ke. no. 12-29-09  
 PS Form 3811, February 2004 Domestic Return Receipt 102595-02-M-1540