



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

April 1, 2010

RE: **PARTIAL INSPECTION  
A&L SALVAGE, LLC C&DD LANDFILL  
COLUMBIANA COUNTY**

**CERTIFIED MAIL**

Mr. Steven Callahan  
A&L Salvage, LLC  
11225 SR 45  
P. O. Box 333  
Lisbon, Ohio 44432

Dear Mr. Callahan:

On March 17, 2010, I, representing the Ohio Environmental Protection Agency (Ohio EPA), conducted a partial inspection of the A&L Salvage, LLC C&DD Landfill (A&L), located at 11225 State Route 45, Columbiana County. The purpose of the inspection was to determine compliance with Ohio Revised Code (ORC) Sections 3714. and 3734., and Ohio Administrative Code (OAC) Chapters 3745-400 and 3745-27. Specifically, the northern sideslope of the facility was inspected since snow had completely melted. The weather was sunny with a slight breeze and a temperature of approximately 60° F. I was accompanied by John Hujar and Harry Smail, representing Ohio EPA. Ron Rager, representing A&L, was present at the facility.

The following violations were observed during this inspection:

1. **Equipment.** During this inspection, the only operable piece of earth moving equipment at A&L was a track hoe. No other operable earth moving equipment, such as a bulldozer or rock truck, was available at the facility to move and spread cover soil or to correct other conditions such as ponding of water or leachate outbreaks on the landfill that have lead to violations being cited at this facility.

A&L is in violation because it has failed to at all times have adequate equipment for operations at the facility. Failure to maintain adequate equipment for operations at the landfill has resulted in a violation of the following:

- a. **OAC Rule 3745-400-11(G):** *"The owner or operator shall have available at all times adequate equipment for operations."*

In order to return to compliance with this rule, the owner or operator must immediately make available adequate equipment at the landfill to conduct all necessary operations and correct all violations.

2. **Fire Prevention.** During this inspection, combustible debris was observed both on the surface of the landfill and on the surface of the landfill exposed in erosion channels. It appeared that the debris had become exposed to the surface through weathering and subsequent loss of cover materials in those areas, which are significant in size.

A&L is in violation because it has failed to maintain cover, using soil, clean hard fill, or other material which is noncombustible, over all combustible debris disposed at the facility. Failure to cover all combustible debris at the landfill has resulted in a violation of the following:

- a. **OAC Rule 3745-400-11(H)**: *"The owner or operator shall operate the facility in a manner that prevents fires by...covering all disposed combustible debris on a weekly basis with soil, clean hard fill, or other material which is noncombustible. For the purpose of this rule, covering means to apply noncombustible material in a manner such that combustible debris is not visible."*

In order to return to compliance with this rule, the owner or operator must immediately cover all combustible materials disposed at the landfill with noncombustible material.

3. **Fire Control.** During this inspection, the only operable piece of earth moving equipment at A&L was a track hoe. No other operable earth moving equipment, such as a bulldozer or rock truck, was available at the facility to move and spread cover soil or to perform other activities that would be required in order to control or extinguish a fire. Further, only a small soil stockpile is currently available on the facility.

A&L is in violation because it has failed to have available at or near the facility, adequate fire control equipment, material, and services to control fire and explosion. Failure to have available at or near the facility, adequate fire control equipment, material, and services to control fire and explosion has resulted in a violation of the following:

- a. **OAC Rule 3745-400-11(M)**: *"The owner or operator shall have available at or near the facility, adequate fire control equipment, material, and services to control fire and explosion."*

In order to return to compliance with this rule, the owner or operator must immediately make available adequate equipment, material, and services at the landfill to control or extinguish a fire.

4. **Leachate Outbreaks.** During this inspection, at least ten large leachate outbreaks were observed near the toe of the slope on the north side of the landfill. Please refer to Attachment 1 for pictures of the leachate outbreaks.

A&L is in violation because it has failed to contain the leachate, manage and dispose the leachate in accordance with applicable regulations, and repair the leachate outbreaks at the facility. Failure to address the leachate outbreaks at the landfill has resulted in a violation of the following:

- a. **OAC Rule 3745-400-11(O)(1):** *"If there is an outbreak of leachate at the surface, the owner or operator shall do all of the following...Contain the leachate."*
- b. **OAC Rule 3745-400-11(O)(2):** *"If there is an outbreak of leachate at the surface, the owner or operator shall do all of the following... Manage and dispose the leachate in accordance with applicable regulations."*
- c. **OAC Rule 3745-400-11(O)(3):** *"If there is an outbreak of leachate at the surface, the owner or operator shall do all of the following...Repair the outbreak."*

In order to return to compliance with these rules, the owner or operator must immediately contain the leachate, manage and dispose the leachate in accordance with applicable regulations, and repair the outbreaks.

5. **Surface Water Management.** During this inspection, erosion channels ranging from one inch to approximately 6 inches in depth were observed on the uppermost portion of the landfill and spread across the north facing sideslope of the landfill.

A&L is in violation because it has failed to control surface water and grade the facility to prevent erosion and the conditions causing erosion on the landfill. Failure to correct the conditions causing erosion through the cover material on the landfill has resulted in violations of the following:

- a. **OAC Rule 3745-400-11(Q)(2):** *"The owner or operator shall control surface and ground water to minimize the generation of leachate in the following manner...The owner or operator shall grade the facility and provide drainage systems to insure minimal infiltration of water through the cover material and cap system as well as erosion of the cover material and cap system."*
- b. **OAC Rule 3745-400-11(Q)(3):** *"The owner or operator shall control surface and ground water to minimize the generation of leachate in the following manner...If ponding or erosion occurs in active or inactive licensed disposal areas, the owner or operator shall correct the conditions causing the ponding or erosion."*

Mr. Steven Callahan  
A&L Salvage, LLC  
April 1, 2010  
Page 4

In order to return to compliance with these rules, the owner or operator must immediately control surface water and grade the facility to prevent erosion and the conditions causing erosion on the landfill.

Please provide written notification to me within 15 days of receiving this letter which documents how the violations listed above have been corrected.

The following were observed and/or discussed during the inspection:

1. Strong hydrogen sulfide/landfill gas odors were detected while on the landfill. These odors were not detected off site during surveillance of areas surrounding the facility.

A&L must continue to make every effort possible to eliminate the conditions leading to the generation of hydrogen sulfide gas, and to control the release of hydrogen sulfide gas from this facility. Failure to eliminate the conditions leading to the generation of hydrogen sulfide gas, and failure to control the release of hydrogen sulfide gas has resulted in odors offensive to the senses and interference with the comfortable enjoyment of life and property of the surrounding community.

Nothing in this letter shall be construed to authorize any waiver from the requirements of any applicable state or federal laws or regulations. This letter shall not be interpreted to release the owner or operator of A&L Salvage, LLC, or others, from responsibility under Chapters 3704., 3714., 3734., or 6111. of the Ohio Revised Code or under the Federal Clean Water or Comprehensive Environmental Response, Compensation, and Liability Acts remedying conditions resulting from any release of contaminants to the environment.

If you have any questions regarding this letter, please feel free to contact me at (330) 963-1274, or preferably, e-mail me at "[jerry.weber@epa.state.oh.us](mailto:jerry.weber@epa.state.oh.us)."

Sincerely,



Jerry W. Weber, R. S.  
Environmental Specialist  
Division of Solid and Infectious Waste Management

JWW:cl  
Attachment

ec: Bruce McCoy, DSIWM-CO      cc: File: [Kurko/CONS/A&L Salvage/COR/15]  
Kristopher Weiss, PIC  
Nick Bryan, AGO  
Lori Barnes, Columbiana County Health Department

1042



1043

2083





**U.S. Postal Service**  
**CERTIFIED MAIL RECEIPT**  
*(Domestic Mail Only; No Insurance Coverage Provided)*

For Delivery information visit our website at [www.usps.com](http://www.usps.com)

Postage	\$	<i>march 17 postmarked  insp  Postmark Here  JWW  1-10</i>
Certified Fee		
Return Receipt Fee (Endorsement Required)		
Restricted Delivery Fee (Endorsement Required)		
Total Postage & Fees	\$	

7009 1680 0000 6381 3682

Sent To	<i>Steve Callahan</i>
Street, Apt. No., or PO Box No.	<i>A + L Salvage</i>
City, State, ZIP+4	

PS Form 3800 August 2004 See Reverse for Instructions

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
<ul style="list-style-type: none"> <li>■ Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.</li> <li>■ Print your name and address on the reverse so that we can return the card to you.</li> <li>■ Attach this card to the back of the mailpiece, or on the front if space permits.</li> </ul>	<p>A. Signature  <i>[Signature]</i> <input checked="" type="checkbox"/> Agent <input type="checkbox"/> Addressee</p> <p>B. Received by (Printed Name) <span style="float: right;">C. Date of Delivery</span>  <i>RON RAGER</i> <span style="float: right;"><i>9/15</i></span></p> <p>D. Is delivery address different from item 1? <input type="checkbox"/> Yes  If YES, enter delivery address below: <input type="checkbox"/> No</p>
<p>1. Article Addressed to:</p> <p>Mr. Steven Callahan  A&amp;L Salvage, LLC  11225 SR 45  P. O. Box 333  Lisbon, Ohio 44432</p>	<p>3. Service Type</p> <input checked="" type="checkbox"/> Certified Mail <input type="checkbox"/> Express Mail <input type="checkbox"/> Registered <input checked="" type="checkbox"/> Return Receipt for Merchandise <input type="checkbox"/> Insured Mail <input type="checkbox"/> C.O.D.
<p>2. Article Number  (Transfer from service label) <i>7009 1680 0000 6381 3682 g. Weber 4-1-10</i></p>	<p>4. Restricted Delivery? (Extra Fee) <input type="checkbox"/> Yes</p>